

AD-A155 895


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
WHITMANS POND DAM (MA...) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV AUG 80


1/2

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A155 695

WEYMOUTH RIVER BASIN
WEYMOUTH, MASSACHUSETTS

WHITMANS POND DAM

MA 00775

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



FILE COPY

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

AUGUST 1980

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

85 6 8 080

REF ID: A66666
REPRODUCED AT GOVERNMENT EXPENSE

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00775	2. GOVT ACCESSION NO. A155695	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Whitmans Pond Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE August 1980
		13. NUMBER OF PAGES 80
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Weymouth River Basin Weymouth, Massachusetts Herring Brook		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is about 60 ft. long between abutments and the maximum height if the dam is about 16 ft. The pond is utilized as a recreational facility. The dam and appurtenant works are judged to be in good physical condition, however, because the spillway can only pass 62 percent of the routed test flood outflow, the dam was given an overall rating of fair. The owner should implement various operating and maintenance measures.		



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02254

REPLY TO
ATTENTION OF:

NEDED

DEC 9 1980

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:

Inclosed is a copy of the Whitmans Pond Dam (MA-00775) Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, Town of Weymouth, Mass.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely,

WILLIAM E. HODGSON, JR.
Colonel, Corps of Engineers
Acting Division Engineer

Incl
As stated

WHITMANS POND DAM

MA 00775

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/1	-



WEYMOUTH RIVER BASIN
WEYMOUTH, MASSACHUSETTS

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT

Identification No: MA 00775
Name of Dam: Whitmans Pond Dam
Town: Weymouth
County and State: Norfolk County, Massachusetts
Stream: Herring Brook
Date of Inspection: 18 April 1980

BRIEF ASSESSMENT

Whitmans Pond Dam is a concrete gravity structure consisting of three basic components: a fish ladder at the left abutment; a 24 ft. long ogee shaped overflow section located just to the right of the fish ladder; and a siphon spillway structure located just right of the overflow section and extending to the right abutment. The siphon spillway structure contains four siphon units having throats measuring 6 ft. by 5 ft. There is a 2.5 ft. square gated sluiceway located on the right side and in the lower part of the overflow section. The dam is about 60 ft. long between abutments and the maximum height of the dam is about 16 ft. measured from downstream river channel bottom to the top of the siphon structure. The crest of the overflow section is 5.8 ft. below the top of dam. The dam was constructed in 1970 as part of a flood control project for the Town of Weymouth, Massachusetts.

Whitmans Pond is utilized as a recreational facility. It is about 7,000 ft. long and has a surface area of about 191 acres at spillway crest level. The drainage area is 12.11 sq. mi. (7,750 acres) and the maximum storage to top of dam is 2,000 acre-ft.; the size classification is thus intermediate. Because a failure of the structure would cause serious damage to the downstream community East Weymouth, with the possibility of the loss of more than a few lives and the probability of excessive economic losses, it has been classified as having a high hazard potential.

Based on the guidelines, the recommended test flood for such a facility is a full Probable Maximum Flood. The test flood inflow was calculated to be 6,850 cfs. The routed test flood outflow of 5,100 cfs overtops the dam by 2.7 ft. The spillways can pass 3,150 cfs or about 62 percent of the routed test flood outflow without overtopping the dam.


The dam and appurtenant works are judged to be in good physical condition, however, because the spillway can only pass 62 percent of the routed test flood outflow, the dam was given an overall rating of fair. The only problem with the physical condition of the dam is the erosion downstream of each abutment.

Within one year after receipt of this Phase I Inspection Report the owner should engage a qualified registered engineer to: (1) perform a detailed

hydraulic and hydrologic study to further assess the need for and means to increase the project discharge capacity; and, (2) perform a seismic investigation and analysis by conventional equivalent static load methods.

The owner should implement the following operating and maintenance measures:

- (1) repair erosion of the left abutment at the downstream end of the left training wall of the fish ladder with compacted gravel fill and locally place riprap in the vicinity of the downstream side of the end of the retaining wall;
- (2) repair the slope behind the right retaining wall on the right abutment with suitable compacted backfill;
- (3) develop a formal surveillance and downstream emergency warning plan, including round-the-clock monitoring during periods of heavy precipitation;
- (4) institute procedures for a biennial technical inspection of the dam and its appurtenant structures; and
- (5) implement a regular periodic maintenance program.



Peter M. Dyson
Project Manager



This Phase I Inspection Report on Whitmans Pond Dam (MA-00775) has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Aramast Mahtesian

ARAMAST MAHTESIAN, MEMBER
Geotechnical Engineering Branch
Engineering Division

Carney M. Terzian

CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division

Richard J. DiBuono

RICHARD DIBUONO, CHAIRMAN
Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar
JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, sub-surface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii
Overview Photo	v
Location Map	vi

REPORT

1. PROJECT INFORMATION

1.1 General	1
a. Authority	1
b. Purpose of Inspection	1
1.2 Description of Project	1
a. Location	1
b. Description of Dam and Appurtenances	1
c. Size Classification	2
d. Hazard Classification	2
e. Ownership	2
f. Operator	2
g. Purpose of Dam	2
h. Design and Construction History	3
i. Normal Operational Procedure	3
1.3 Pertinent Data	3

2. ENGINEERING DATA

2.1 Design Data	7
2.2 Construction Data	7
2.3 Operation Data	7
2.4 Evaluation of Data	7

<u>Section</u>	<u>Page</u>
3. VISUAL INSPECTION	
3.1 Findings	8
a. General	8
b. Dam and Appurtenant Structures	8
c. Reservoir Area	9
d. Downstream Channel	9
3.2 Evaluation	10
4. OPERATIONAL AND MAINTENANCE PROCEDURES	
4.1 Operational Procedures	11
a. General	11
b. Description of any Warning System in Effect	11
4.2 Maintenance Procedures	11
a. General	11
b. Operating Facilities	11
4.3 Evaluation	11
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	
5.1 General	12
5.2 Design Data	12
5.3 Experience Data	12
5.4 Test Flood Analysis	13
5.5 Dam Failure Analysis	14
6. EVALUATION OF STRUCTURAL STABILITY	
6.1 Visual Observation	15
6.2 Design and Construction Data	15
6.3 Post-Construction Changes	15
6.4 Seismic Stability	15

<u>Section</u>	<u>Page</u>
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	16
a. Condition	16
b. Adequacy of Information	16
c. Urgency	16
7.2 Recommendations	16
7.3 Remedial Measures	16
a. Operation and Maintenance Procedures	16
7.4 Alternatives	17

APPENDIXES

APPENDIX A - INSPECTION CHECKLIST

APPENDIX B - ENGINEERING DATA

APPENDIX C - PHOTOGRAPHS

APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS

APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL
INVENTORY OF DAMS

WHITMANS POND DAM



OVERVIEW FROM LEFT ABUTMENT

PHASE I INSPECTION REPORT

WHITMANS POND DAM MA 00755

SECTION 1 - PROJECT INFORMATION

1.1 General

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Louis Berger & Associates, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Authorization and notice to proceed was issued to Louis Berger & Associates, Inc. under a letter of 28 March 1980 from William E. Hodgson, Jr., Colonel, Corps of Engineers. Contract No. DACW33-80-C-0043, has been assigned by the Corps of Engineers for this work.

b. Purpose of Inspection.

(1) Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

(2) Encourage and assist the States to initiate quickly effective dam safety programs for non-Federal interests.

(3) Update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location. Whitmans Pond Dam is located in Norfolk County in the Town of Weymouth in eastern Massachusetts. The dam is situated about 850 ft. upstream of Iron Hill Dam and the headwaters of Herring Brook and about 1.3 mi. upstream of the confluence of Herring Brook and the Weymouth Back River. The dam can be reached via a side Street off Lake Street or via Iron Hill Street. The dam is shown on U.S.G.S. Quadrangle, Weymouth, Massachusetts with coordinates approximately at N 42° 12 ' 39", W 70° 55' 49".

b. Description of Dam and Appurtenances. The Whitmans Pond Dam is a 60 ft. long and 16 ft. high concrete gravity dam consisting of three major elements; a fish ladder, an overflow section, and a siphon spillway structure containing four siphon units. A pedestrian bridge spans the approach channel just upstream of the spillway structures.

At the left side of the dam there is a concrete fish ladder with a clear opening of 3 ft. and a length of approximately 75 ft. The ladder consists basically of two reinforced concrete training walls founded on bedrock. There are slots in the concrete walls to accomodate wooden baffles set at approximately two foot intervals. The elevation of the base slab between the walls varies from 56.9 at the downstream end to 64.6 at the upstream end. The top of the retaining walls are at elevation 72.4.

Just to the right of the fish ladder is a concrete ogee overflow section which has an overall width of 25 ft. and net width of 24 ft. The crest of the overflow section is at elevation 66.6. The training walls on either side of the spillway are 5.8 ft. high. On the right side of the overflow section, at the channel bottom is a sluiceway through the base of the ogee section. The sluiceway is 2.5 ft. square and has an invert elevation of 58.6 ft. The control for the sluiceway is a 2.5 ft. square sluice gate which is hand operated from a small bridge over the right side of the overflow section.

To the right of the overflow section is the siphon spillway structure which extends to the right abutment of the dam. This structure is 29 ft. wide and has four siphon units. Each unit is 6 ft. wide by 5 ft. high at its throat. The interior crest elevations are 66.8 for unit one, 66.6 for unit two, 66.7 for unit three, and 66.9 for unit four as shown in the design drawings in Appendix B. The top of the siphon spillway structure is at elevation 72.4. Both the siphon spillway structure and the ogee spillway section are founded on bedrock.

There is an 80 ft. long reinforced concrete girder foot bridge spanning the dam structure immediately upstream of the crest of the spillway. The bridge is supported on each end by reinforced concrete abutments and by a central pier of reinforced concrete founded on bedrock in the stream channel upstream of the dam. The bridge deck varies from elevation 80 on the left abutment to elevation 77.5 on the right abutment.

c. Size Classification. Whitmans Pond Dam has a hydraulic height of about 16 ft. above downstream river level, and impounds a normal storage of about 550 acre-ft. to spillway crest level and a maximum of about 2,000 acre-ft. to top of dam. In accordance with the size and capacity criteria given in Recommended Guidelines for Safety Inspection of Dams, the project falls into the intermediate category on the basis of capacity and is therefore classified accordingly.

D. Hazard Classification. A breach failure of Whitmans Pond Dam would release water into Iron Hill Reservoir, down Herring Brook and through the heavily built-up community of East Weymouth to the Weymouth Back River. It is estimated that a breach of the dam's abutment area would flood a school building, four industrial buildings, about twenty-three commercial buildings and about seven houses to depths ranging from 1 to 7 ft., all within a distance of about 4,000 ft. from the dam. In addition several local streets would be flooded. No significant flooding is estimated due to the spillway discharge alone. In accordance with the Recommended Guidelines for Safety Inspection of Dams, Whitmans Pond Dam has therefore been classified as having a high hazard potential, since failure may cause damage to more than a small number of habitable structures and excessive economic losses, with the potential for the loss of more than a few lives.

e. Ownership. Whitmans Pond Dam is owned by the Town of Weymouth, Massachusetts.

f. Operator. The operator of the dam is Mr. Frank Lagrotteria, Town Engineer, Town of Weymouth, Department of Public Works, 120 Winter Street, Weymouth, Massachusetts 02188. Telephone: 617-337-5100.

g. Purpose of Dam. Whitmans Pond Dam impounds a body of water used for recreational purposes. The dam together with the Iron Hill Dam and the Herring Brook Flood Control Conduit serves to provide flood control protection to the Town of Weymouth.

h. Design and Construction History. The Whitmans Pond Dam was designed by Metcalf and Eddy, Engineers, Boston, Massachusetts and was constructed in 1970. It replaced a concrete structure which was built in 1935, a few feet downstream from the site at which another dam had been located for more than 120 years. The present dam was constructed together with the Iron Hill Dam and the Herring Brook Flood Control Conduit as a means of reducing flood damage in the Town of Weymouth.

i. Normal Operating Procedures. There are no written operating procedures for the facility. The only operating devices are the controls for the low level sluice way, stoplogs in the upstream entrance to the fish ladder, and emergency air vents for each of the siphon units. These air vents consist of cast-iron pipes which are normally sealed with a bolted, gasketed, blind flange cover and are used for venting the siphons should the automatic air vents for the siphons not function.

1.3 Pertinent Data.

a. Drainage Area. The drainage area contributing to Whitmans Pond is located at the beginning of Herring Brook. The drainage area encompasses a total of about 12.11 sq. mi., (7,750 acres), of which about 191 acres is occupied by the pond. The longest circuitous stream course leading to the dam is about 6.6 miles long with an elevation difference of about 104 ft., or at a slope of about 15.7 ft. per mile. The drainage area has a length of about 6 miles and an average width of about 2.8 miles. The topography in the basin is best described as flat and coastal. The drainage basin consists of a mixture of forested areas and heavily builtup urban areas. Weymouth Great Pond having a drainage area of about 2.89 sq. mi. is located in the upper reaches of the drainage area and should have a substantial effect on the inflow to Whitmans Pond.

b. Discharge at Damsite.

(1) Outlet Works Conduit. There is a 2.5 ft. square sluice gate located in the overflow section and to the left of the siphon spillway section of the dam. The bottom of the sluice gate is near the channel bottom and this facility could be used for lowering the pond. With the water surface level at top of dam, elevation 72.4 ft. it is estimated that the sluice gate would be capable of discharging about 95 cfs.

(2) Maximum Known Flood at Damsite. No records are available of flood flows into Whitmans Pond or of spillway releases and surcharge heads, since the existing dam was constructed. However, in the Preliminary Engineering Study for the dam, it was estimated that the maximum discharge over the previous dam at Whitmans Pond was 1,100 cfs during hurricane "Diana" in August of 1955. It was estimated that the surcharge during that storm peaked at elevation 71.5 ft.

(3) Ungated Spillway Capacity at Top of Dam. The ungated spillway capacity at top of dam, elevation 72.4, is 3,150 cfs.

(4) Ungated Spillway Capacity at Test Flood Elevation. The ungated spillway capacity at test flood elevation 75.1 ft. is about 4,550 cfs.

(5) Gated Spillway Capacity at Normal Pool. Not Applicable

(6) Gated Spillway Capacity at Test Flood Elevation. Not Applicable

(7) Total Spillway Capacity at Test Flood Elevation. The total spillway capacity at test flood elevation is the same as (4) above, 4,550 cfs at elevation 75.1.

(8) Total Project Discharge at Top of Dam. Assuming the sluice gate to be open, the total project discharge at top of dam, elevation 72.4 is about 3,245 cfs.

(9) Total Project Discharge at Test Flood Elevation. The total project discharge at test flood elevation is 5,100 cfs at elevation 75.1.

c. Elevation (ft. N.G.V.D.)

- (1) Streambed at toe of dam - 56.4 \pm
- (2) Bottom of cutoff - 54.0
- (3) Maximum tailwater - unknown
- (4) Recreation pool - 66.6
- (5) Full flood control pool - Top of dam - 72.4
- (6) Spillway crest - 66.6
- (7) Design surcharge (Original Design) - 70.6 (Approximate)
- (8) Top of dam - 72.4
- (9) Test flood surcharge - 75.1

d. Reservoir (Length in feet)

- (1) Normal pool - 7,000
- (2) Flood control pool - 8,000
- (3) Spillway crest pool - 7,000
- (4) Top of dam - 8,000
- (5) Test flood pool - 8,300

e. Storage (acre-feet)

- (1) Normal pool - 550
- (2) Flood control pool - 2,000
- (3) Spillway crest pool - 550
- (4) Top of dam - 2,000
- (5) Test flood pool - 2,925

f. Reservoir Surface (acres)

- (1) Normal pool - 191
- (2) Flood-control pool - 306
- (3) Spillway crest - 191
- (4) Top of dam - 306
- (5) Test flood pool - 362

g. Dam

- (1) Type - Mass Concrete, Gravity
- (2) Length - 60 ft.
- (3) Height - 16 ft.
- (4) Top Width - Varies - about 19 ft. at siphon section
- (5) Side Slopes - Vertical sides at siphon structure
- (6) Zoning - Not Applicable
- (7) Impervious Core - Not Applicable
- (8) Cutoff - Concrete keys in ledge
- (9) Grout curtain - Unknown

i. Spillway

- (1) Type - Combination: Concrete ogee overflow section, fish ladder and, four unit siphon spillway section
- (2) Length of Weir - Ogee Section: 24 ft.
Fish Ladder : 3 ft.
Siphons: Four with 6 ft. x 5 ft. throats each
- (3) Crest Elevation - Ogee Section: 66.6
Siphons: four at elevations 66.6, 66.7, 66.8 and 66.9
- (4) Gates - None
- (5) U/S Channel - Natural channel with concrete walls in immediate vicinity of dam.
- (6) D/S Channel - Natural channel impounded by Iron Hill Dam located about 850 ft. downstream.

(7) General - None

j. Regulating Outlets

(1) Invert - 58.6

(2) Size - 2.5 ft. x 2.5 ft.

(3) Description - Sluiceway opening through overflow section.

(4) Control Mechanism - Hand Operated Sluice Gate.

(5) Other - None

SECTION 2 - ENGINEERING DATA

2.1 Design Data

The present Whitmans Pond Dam replaced an earlier dam located in the same vicinity as the present dam. The present dam was designed by Metcalf & Eddy, Engineers (now Metcalf & Eddy, Inc.) of Boston, Massachusetts. Copies of drawings which are pertinent to consideration of dam safety are included in Appendix B. Hydrologic, hydraulic, and soils data relating to the design of the dam was located in the Town Engineer's Office in Weymouth, Massachusetts, and has been reviewed by the inspection team.

2.2 Construction Data

The dam was built in 1970 as part of the Flood Control Conduit and Siphon Spillways, Herring Brook Project by the Commonwealth of Massachusetts, Department of Public Works, Division of Waterways, but no construction records have been recovered.

2.3 Operation Data

No engineering operational data was disclosed for the dam.

2.4 Evaluation

a. Availability. The plans, hydrologic data, hydraulic data and borings logs located in the Town Engineer's Office supplemented by the visual observations of the inspection team, form the basis for the information presented in this report.

b. Adequacy. Sufficient engineering data was recovered to assess the structural stability of the concrete dam. No data was available to assess the safety of the earth abutment zones. The overall adequacy of the dam was assessed on the basis of the data recovered supplemented by visual inspection, past performance history and engineering judgement.

c. Validity. The validity of the engineering data acquired covering the dam is considered acceptable and is not challenged.

SECTION 3 - VISUAL INSPECTION

3.1 Findings

a. General. The visual inspection of Whitmans Pond Dam took place on 18 April 1980. On that date water was flowing over the ogee crest spillway, through the fish ladder and through at least two of the four siphon units. However, the rate of flow over the dam was relatively low. There was no evidence of any major problems with the dam. The physical condition of the dam was judged to be good.

b. Dam and Appurtenant Structures. Whitmans Pond Dam is a concrete gravity structure consisting of three basic components: a fish ladder on the left abutment; an ogee shaped overflow section located just to the right of the fish ladder; and a siphon spillway structure containing four siphon units. The dam has a maximum height of 16 ft. from channel bottom to the top of the siphon structure and the distance from the left abutment to the right abutment is about 60 ft. The fish ladder has a clear opening of 3 ft. and is about 75 ft. long. The ogee shaped overflow section has a total crest length of 25 ft. with a clear opening length of 24 ft. The crest of the overflow section is 5.8 ft. below the top of the dam. On the right side of the overflow section, at channel bottom is a sluiceway which is controlled by a 2.5 ft. square sluice gate. The control mechanism for the sluice gate is hand operated from a small bridge which spans part of the overflow section. The siphon spillway structure located to the right of the overflow section is 29 ft. wide and has four siphon units. Each unit is 6 ft. wide by 5 ft. high at its throat and the interior crest elevations are 66.8 for unit one, 66.6 for unit two, 66.7 for unit three, and 66.9 for unit four. Just upstream of the dam, a reinforced concrete girder foot bridge spans the approach channel.

Bedrock outcrops consisting of very massive and only slightly jointed granite are located on the right abutment above the dam. It appears the dam is founded on bedrock since the design drawings contain logs of test borings cored into bedrock.

The downstream face of the dam as shown in Photo's #1,2,3 and 4 is in good condition. Heavy stone revetment downstream of the training wall to the right of the outlet end of the siphon structure has been displaced and there is minor erosion downstream of the right training wall (see Photo #5).

Photos 6 and 7 show the concrete fish structure on the left abutment. The concrete is in generally excellent condition. There is, however, erosion of the downstream earth slope behind the left training wall of the fish ladder.

Photo #8 is a view of the right training wall of the approximately 350 ft. long spillway approach channel. This rubble masonry wall is part of the older dam which was replaced in 1935. The wall appears to be in good condition in spite of the fact that the joints are not mortared.

A bridge which is in fair condition spans the spillway approach channel. The spillway approach channel training walls are in generally excellent condition with no evidence of movement or distress of any kind. The concrete is in excellent condition with only minor random cracking observed and minor efflorescence (see Photo Nos. 9 & 10). The downstream face of the concrete ogee overflow section appears to be in good condition (see Photo No. 11).

The outlet end of the siphon spillway structure appears to be in good condition. As shown on Photo 12, only two of the four siphons were operating at the time of the inspection.

There is a sluiceway under the ogee over flow section at the intersection with the siphon structure as shown on Photo 13. Though the sluice gate was not operated during the time of inspection it was reported to be in good working condition. There is an approximately 3 ft. long by $\frac{1}{2}$ in. to 1 in. wide crack in the concrete to the left of the sluiceway on the siphon structure wall.

c. Reservoir Area. The pond's shoreline upstream of the dam appears to be stable with no evidence of sliding. The area above the easterly side of the pond is a densely developed residential area. The north shore of the pond is occupied in part by a Federal housing project and the remainder by other residential development. The land along the westerly shore of the pond is densely developed. The shore along the southern portion of the pond is bordered by extensive gravel pit areas.

d. Downstream Channel. The river slopes downstream of the dam on both the left and right embankments were inspected and no seepage was emanating from the slopes. Discharges from Whitmans Pond Dam flow into Iron Hill Reservoir which is a small impoundment about 850 ft. long and about 100 ft. wide. Iron Hill Reservoir is impounded by Iron Hill Dam which is also a concrete gravity structure with siphon spillways. Herring Brook is located below the Iron Hill Dam and extends downstream for a distance of about 3,000 ft. until it reaches the Weymouth Back River just below the Penn Central Railroad. At the toe of Iron Hill Dam there is a flood control conduit which parallels Herring Brook for a distance of about 1,800 ft. and ends a short distance downstream of Broad Street. The flood control conduit has a carrying capacity of about 2,500 cfs. It was constructed as part of the flood control project and together with the Whitmans Pond Dam and the Iron Hill Dam protects the heavily built-up community of East Weymouth. Part of the East Weymouth community is located in the flood plain of Herring Brook. Below Broad Street the old Herring Brook channel and the flood control conduit join together and flow through a recently constructed open channel, and then under the Penn Central Railroad, and into the Weymouth Back River.

3.2 Evaluation

The visual inspection has adequately revealed key characteristics of the dam as they may relate to its stability and integrity. The dam and appurtenant works were judged to be in good physical condition. Minor erosion of the right earth abutment was noted at the downstream end of the dam just beyond the riprap protection beyond the siphon spillway structure. There is also erosion of the left earth abutment at the downstream end of the fish ladder. There is no regular periodic maintenance program.

SECTION 4 - OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 Operational Procedures

a. General. The dam is owned and operated by the Town of Weymouth. It is operated in conjunction with the Iron Hill Dam located about 850 ft. downstream as a means of flood protection for the community located downstream and for maintaining water levels in Whitmans Pond for recreational uses.

b. Description of any Warning System in Effect. No warning system is in effect at Whitmans Pond Dam.

4.2 Maintenance Procedures

a. General. There is no documented periodic maintenance program in effect at Whitmans Pond Dam. There are, however, a few items which require periodic maintenance, such as: the removal of brush growth from the abutments; the upkeep of the concrete in the spillway structures and training walls; keeping the overflow section spillway free of debris; keeping the trash racks at the entrance of the siphon spillways free from debris; surveillance of the abutment slopes with regards to erosion; and maintenance of the sluice gate.

b. Operating Facilities. The only operating facility for the dam is the sluice gate which appears to be well maintained and was reported to be in operating condition.

4.3 Evaluation

Overall maintenance of the facility is good. Specific maintenance items are evaluated as follows; there was very little brush growth on the slopes of the abutments; there was only a small amount of debris on the trash racks at the entrance to the siphon spillways; the concrete appeared to be in good condition; there was a small amount of erosion noted in the downstream channel embankment on the right side of the channel; and there was erosion of the abutment slopes at the lower end of the left training wall of the fish ladder. The owner should establish a formal downstream warning system for the dam in the event of an emergency.

SECTION 5 : EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

5.1 General.

Whitmans Pond Dam is a mass concrete dam consisting of three major elements; a fish ladder, an overflow section, and a siphon spillway structure containing four siphon units. The dam impounds a normal storage of about 550 acre-ft. with provisions for an additional 1,450 acre-ft. of capacity in its surcharge space to the top of dam. It is basically a low surcharge - high spillage facility used to impound water for recreational purposes and to provide flood control protection for a downstream community. The spillways are capable of discharging about 3,150 cfs with the surcharge to the top of dam. The general topographic characteristics of the 12.1 sq. mi. drainage basin is best described as flat and coastal, which rises from elevation 66.6 at spillway crest to elevation 170. The drainage area contains a mixture of forested areas and heavily developed urban areas. Weymouth Great Pond which has a drainage area of about 2.9 sq. mi. is located in the upper reaches of the drainage area. Because of the substantial volume of storage available in Weymouth Great Pond, the drainage area above the outlet of the pond was not included in calculating the test flood for Whitmans Pond Dam. Thus the net area used for calculating the test flood inflow was 9.2 sq. mi.

5.2 Design Data.

Three reports were located which contain preliminary hydrologic and hydraulic design data for the dam. The titles of these reports are as follows: (1) Town of Weymouth, Massachusetts, Report to Drainage Committee Upon Storm Water Drainage, dated March 11, 1957; (2) Town of Weymouth, Massachusetts, Appendix to Report to, Drainage Committee Upon Storm Water Drainage, dated March 11, 1957; and (3) Site Investigations for Flood Control Works at Herring Brook and Whitmans Pond Outlet, Weymouth, Massachusetts, dated June 20, 1969.

All three of the reports were prepared by Metcalf and Eddy, Engineers, Boston, Massachusetts. The reports were reviewed by the inspection team and are on file at the Weymouth Town Engineer's Office. The following was extracted from the 1969 Report: "According to the 1957 Report, the peak rate of runoff which could be expected to Whitmans Pond was estimated at 5,100 cfs. This is about 75 percent of the "maximum" flood peak indicated by using the Kinnison-Colby formula. Coefficients used in the formula are based on the area being developed to its estimated fullest extent, thus producing the maximum expected flows.....Using the storage available in Whitmans Pond and the flood routing method of computation, the peak rate of outflow to be expected from the pond was estimated at approximately 2,500 cfs".

5.3 Experience Data.

No records are available in regard to past operation of the reservoir, nor of surcharge encroachments and flows through the spillway of the present dam. However, in the 1957 Reports mentioned above, it was estimated that the maximum discharge over the dam which preceded the

present dam at Whitmans Pond was 1,100 cfs during hurricane "Diane" of Aug. 18-19, 1955. It was estimated that the surcharge elevation during the storm peaked at about elevation 71.5 ft.

5.4 Test Flood Analysis.

Hydrologic and hydraulic characteristics of Whitmans Pond Dam and drainage area were evaluated in accordance with the criteria given in Recommended Guidelines for Safety Inspection of Dams. As indicated in Section 1.2, paragraphs c and d, Whitmans Pond Dam is classified as intermediate in size and has a high hazard potential. The recommended test flood for hydraulic evaluation of such a dam is a full Probable Maximum Flood, (PMF).

Precipitation data were obtained from Hydrometeorological Report No. 33, which for this area of Massachusetts is about 23.5 in of 6 hour maximum rainfall over a 10 square mile area. This value was then reduced by 20 percent to allow for basin size, shape and fit factors, and an additional 0.4 in. was deducted for infiltration losses. The six hour rainfall was distributed into one hour incremental periods as suggested in COE Publication EC 1110-2-1411.

A triangular incremental unitgraph was assumed for the inflow hydrograph using a computed lag time of 13.2 hours to derive a time-to-peak for the triangular hydrograph of 11.23 hours (see computations on Sheets D-11 and D-12, Appendix D). The test flood hydrograph is shown on Sheet D-13, Appendix D, indicating a peak inflow of about 6,850 cfs or a CSM value of about 565 cfs. This value is in close agreement with the peak inflow derived by the Kinnison-Colby formula in the 1957 Report and is also in close agreement with the envelope curve value given in the March 1978 Preliminary Guidance for Estimating Maximum Probable Discharges for Flat and Coastal Areas for a drainage area of 9.2 sq. mi.

Discharge tables and curves for the spillway facilities and for over the top of the dam are shown on Sheets D-6 thru D-10, Appendix D. The discharge through the 2.5 ft. square sluice has been neglected.

Flood routings were performed for both the test flood and a $\frac{1}{2}$ PMF. Results of these routings are shown on Sheets D-13 and D-14, Appendix D, and are summarized as follows:

<u>Flood Magnitude</u>	<u>Routed Test Flood Inflow (cfs)</u>	<u>Maximum Res. El (ft. NGVD)</u>	<u>Max. Head Over Dam (ft.)</u>	<u>Routed Test Flood Outflow (cfs)</u>
PMF (Test Flood)	6,850	75.1	2.7	5,100
$\frac{1}{2}$ PMF	3,425	70.5	None	2,480

From the above table it can be seen that the project will not pass the routed test flood outflow without overtopping the dam by 2.7 ft. The project, however, can handle about 62 percent of the routed test outflow without overtopping the dam.

5.5 Dam Failure Analysis.

Whereas the dam is a relatively low massive concrete structure, it was assumed that the most likely place for failure would be in the abutment area. For this analysis a 25 ft. wide section of the abutment was assumed to fail. With the water surface level at top of dam and using an orifice formula, the discharge through the failed section was calculated to be 3,370 cfs. The spillway discharge at the time of failure would be about 3,150 cfs resulting in a total discharge of about 6,500 cfs.

The outflow from Whitman Pond Dam discharges into Iron Hill Reservoir, passes over Iron Hill Dam and thence along Herring Brook through the heavily built-up community of East Weymouth to the Weymouth Back River. Below Iron Hill Dam there is a flood control conduit which carries flows from the Iron Hill Dam for a distance of about 1,800 ft. to an open channel about 1,400 ft. upstream from the Penn Central Railroad. The railroad is supported by a high embankment through which passes an 8 ft. wide by 11 ft. high box culvert, and two 10 ft. dia. concrete pipes, which carry flows from Herring Brook to the Weymouth Back River. It is estimated that the breach discharge would be about 5,800 cfs at the railroad crossing and that the stage in the brook would be about at elevation 27, which is a rise of about 12 ft. above that to be expected from the spillway discharge. Water would be pooled over more than 50 percent of the reach between Iron Hill Dam and the Penn Central Railroad causing flooding of the Pingree School up to a depth of 7 ft., and flooding four industrial buildings, seven commercial buildings and a few houses all located downstream of Broad Street to a depth ranging between 1 and 5 ft. It is estimated that no significant flooding of structures would exist in this area due to the spillway discharge alone. Above Broad Street the flood control conduit would carry about 2,500 cfs of the breach discharge and the remaining discharge of 4,000 cfs would travel down the original Herring Brook Channel. It is estimated that about 16 commercial buildings and about 6 houses would be flooded by the breach discharge to depths ranging from 1 to 5 ft. In addition to the flooding of structures several streets would be flooded in the damage reach. Based upon the carrying capacity of the flood control conduit and the original Herring Brook channel it is estimated that only minor flooding of the area between Broad Street and the Iron Hill Dam would occur due to the maximum spillway discharge of 3,150 cfs.

In summary, a school building, four industrial buildings, about 23 commercial buildings, and about 7 houses, as well as several local streets are within the area of potential flooding. Therefore, in accordance with the Recommended Guideline for Safety Inspection of Dams the project is classified as having a high hazard potential. There is also the potential for the loss of more than a few lives. The area of potential flooding is shown in Appendix D, page D-19.

SECTION 6 - EVALUATION OF STRUCTURAL STABILITY

6.1 Visual Observations

There are no design calculations available for review of the structural stability of the dam and appurtenant structures; however, the relatively wide base slab for the ogee section with respect to its height and the fact that it is founded on a sound granite bedrock, plus the absence of any distress or displacements in the structure indicate that the dam is stable in its present state. However, some minor repair of riprap and of eroded areas as described in Section 7 should be undertaken.

6.2 Design and Construction Data

Design drawings for the dam and the Herring Brook Flood Control conduit consisting of twenty-two sheets were available for review. These sheets show the details for the design of the structure as well as the nature of the foundation soil and rock conditions beneath the structure as revealed by approximately twenty-two (22) borings taken at this site and at the Iron Hill Dam site. Although calculations pertaining to the stability of the concrete gravity sections were not available for review, it may be concluded on the basis of the design drawings and the visual inspection that the gravity ogee overflow section and spillway siphon structure are presently in a stable condition.

6.3 Post Construction Changes

There are no records of any major post construction changes made to the dam over the course of its history. The dam was constructed in 1970 and replaced an older dam which formerly existed at the site. One remnant of the older dam is a masonry rubble gravity training wall on the right abutment approach channel. This retaining wall appears to be in good condition even though the joints are not mortared.

6.4 Seismic Stability

The dam is located in Seismic Zone No. 3. Phase I Guidelines recommend, as a minimum, that suitable analysis made by conventional equivalent static load methods should be on record for dams in Zone No. 3. As far as can be determined, no such analysis has been made.

SECTION 7

ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. On the basis of the Phase I visual examination, Whitmans Pond Dam is judged to be in good physical condition; however, because the spillway will only pass 62 percent of the routed test flood outflow, the dam has been given an overall rating of fair.

b. Adequacy of Information. Though the lack of in-depth engineering data did not allow for a definitive review, the information that was recovered, together with the visual inspection, was considered adequate for the purpose of making an assessment of the performance of the dam.

c. Urgency. The recommendations and remedial measures enumerated below should be implemented by the owner within one year after receipt of this Phase I Inspection Report.

7.2 Recommendations

It is recommended that the owner engage a qualified engineer to make investigations and studies of the following.

(1) Perform a detailed hydraulic and hydrologic study to further assess the need for and means to increase the project discharge capacity.

(2) Make a seismic investigation of the dam and analysis by conventional equivalent static load methods.

7.3 Remedial Measures

a. Operating and Maintenance Procedures.

(1) Repair erosion at the downstream end of the left training wall of the fish ladder with compacted gravel fill and locally place riprap in the vicinity of the water surface on the downstream side of the end of the retaining wall.

(2) Repair the slope behind the right retaining wall on the right abutment with suitable compacted earthfill.

(3) Develop an "Emergency Action Plan" that will include an effective preplanned downstream warning system, locations of emergency equipment, materials and manpower, authorities to contact and potential areas that require evacuation. The plan will also include round-the-clock monitoring of the project during periods of heavy precipitation.

(4) Institute procedures for an biennial technical inspection of the dam and its appurtenant structures.

(5) Implement a regular periodic maintenance program.

7.4 Alternatives

There are no feasible alternatives to the above recommendations.

Appendix A
Inspection Checklist

VISUAL INSPECTION CHECKLIST
PARTY ORGANIZATION

PROJECT Whitmans Pond Dam DATE 18 April 1980
OWNER: Town of Weymouth, MA. TIME 1:30 PM
WEATHER Clear/Warm
W.S. ELEV. 70.0 U.S. DN.S.

PARTY:

- | | |
|--------------------------------|--------------------------|
| 1. <u>Peter B. Dyson</u> | 6. <u>Robert Millett</u> |
| 2. <u>Pasquale E. Corsetti</u> | 7. _____ |
| 3. <u>Roger F. Berry</u> | 8. _____ |
| 4. <u>Carl J. Hoffman</u> | 9. _____ |
| 5. <u>William S. Zoino</u> | 10. _____ |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Hydrologic</u>	<u>Roger F. Berry</u>	<u>LBA</u>
2. <u>Structures/Hydraulics</u>	<u>Carl J. Hoffman</u>	<u>LBA</u>
3. <u>Geotechnical</u>	<u>William S. Zoino</u>	<u>GZA</u>
4. <u>General Features</u>	<u>Peter B. Dyson</u>	<u>LBA</u>
5. <u>General Features</u>	<u>Pasquale E. Corsetti</u>	<u>LBA</u>
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

LBA- Louis Berger & Associates, Inc.
GZA- Goldberg-Zoino & Associates, Inc.

PERIODIC INSPECTION CHECKLIST

PROJECT Whitmans Pond Dam DATE 18 April 1980

PROJECT FEATURE Sluiceway (low level outlet) NAME

DISCIPLINE Hydraulics/Structures NAME Carl J. Hoffman

AREA EVALUATED	CONDITIONS
----------------	------------

OUTLET WORKS - TRANSITION AND CONDUIT

General Condition of Concrete	Good
Rust or Staining on Concrete	None
Spalling	None
Erosion or Cavitation	None
Cracking	None
Alignment of Monoliths	NA
Alignment of Joints	NA
Numbering of Monoliths	NA

PERIODIC INSPECTION CHECKLIST

PROJECT Whitmans Pond Dam DATE 18 April 1980
 PROJECT FEATURE Ogee Shaped Spillway NAME _____
 DISCIPLINE Hydraulics/Structures NAME Carl J. Hoffman

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	

a. Approach Channel

General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Approach Channel	Not Visible

b. Weir and Training Walls

General Condition of Concrete	Good
Rust or Staining	Minor
Spalling	None
Any Visible Reinforcing	None
Any Seepage or Efflorescence	None
Drain Holes	NA

c. Discharge Channel

General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Channel	Not Visible
Other Obstructions	None

PERIODIC INSPECTION CHECKLIST

PROJECT Whitmans Pond Dam DATE 18 April 1980
 PROJECT FEATURE Siphon Spillways NAME _____
 DISCIPLINE Hydraulics/Structures NAME Carl J. Hoffman

AREA EVALUATED	CONDITIONS
----------------	------------

OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS

a. Approach Channel

General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Approach Channel	Not Visible

b. Weir and Training Walls

General Condition of Concrete	Good
Rust or Staining	Minor
Spalling	None
Any Visible Reinforcing	None
Any Seepage or Efflorescence	None
Drain Holes	NA

c. Discharge Channel

General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Channel	Not Visible
Other Obstructions	None
Minor cracking of concrete	

PERIODIC INSPECTION CHECKLIST

PROJECT: Whitmans Pond Dam

DATE: 18 April 1980

AREA EVALUATED

CONDITIONS

Dam Embankment	N/A
Dike Embankment	N/A
Outlet Works - Intake Channel and Intake Structure	N/A
Outlet Works - Control Tower	N/A
Outlet Works - Outlet Structure and Outlet Channel	N/A
Outlet Works - Service Bridge	N/A

Appendix B
Engineering Data


COMMONWEALTH OF MASSACHUSETTS DEPARTMENT OF PUBLIC WORKS DIVISION OF WATERWAYS PROPOSED FLOOD CONTROL AND SIPHON SPILLWAY HERRING BROOK WEYMOUTH, MASSACHUSETTS

INDEX TO DRAWINGS

GENERAL NOTES

1. ALL ELEVATIONS ARE IN FEET ABOVE MEAN-SEA LEVEL.
2. LOCATIONS OF UTILITIES AND EXISTING STRUCTURES ARE APPROXIMATE. EXACT LOCATIONS ARE TO BE DETERMINED BY THE CONTRACTOR IN THE FIELD.
3. FOR NOTES OF TEST BORINGS SEE SHEET 21.
4. FOR GENERAL STRUCTURAL NOTES SEE SHEET 20.
5. SURVEY INFORMATION IS CONTAINED IN FIELD BOOK #1059 OF THE DEPARTMENT OF PUBLIC WORKS, DIVISION OF WATERWAYS.

SHEET NO.	TITLE
1	TITLE SHEET
2	WHITMANS POND - SITE PLAN
3	IRON HILL DAM - SITE PLAN
4	IRON HILL DAM - PLAN AND DETAILS
5	IRON HILL DAM - CONDUIT PROFILE
6	WHITMANS POND - PLAN
7	WHITMANS POND - SECTIONS I
8	WHITMANS POND - SECTIONS II
9	WHITMANS POND - SECTIONS III
10	WHITMANS POND - SECTIONS IV
11	WHITMANS POND - SECTIONS V
12	WHITMANS POND - SECTIONS AND DETAILS
13	IRON HILL DAM - PLAN
14	IRON HILL DAM - SECTIONS I
15	IRON HILL DAM - SECTIONS II
16	IRON HILL DAM - SECTIONS III
17	IRON HILL DAM - CONDUIT SECTIONS
18	WHITMANS POND - BRIDGE PLAN AND SECTIONS
19	WHITMANS POND - BRIDGE SECTIONS
20	IRON HILL DAM - STRUCTURAL STANDARDS
21	BORING LOGS I
22	BORING LOGS II



LOCATION PLAN


SCALE IN FEET

OF MASSACHUSETTS F PUBLIC WORKS WATERWAYS CONTROL CONDUIT N SPILLWAYS G BROOK MASSACHUSETTS



LEGEND

59.7	SPOT ELEVATION
---62---	EXISTING CONTOUR
---62---	NEW CONTOUR
---	EASEMENT LINE
---	PROPERTY LINE
---	SURVEY LINE
△A	SURVEY POINT
⊙ B-1 EL. 73.6	BORING NUMBER AND GROUND ELEVATION
---	FENCE
◇ HYD.	FIRE HYDRANT
8" W	WATER
2" G	GAS
D	DRAIN
C.B. 11	CATCH BASIN
416	BUILDING AND NUMBER
26"	TREE AND TRUNK SIZE
SECTION CUT NUMBER DESIGNATION SHEET UPON WHICH SECTION APPEARS	SECTION CUT
	EXISTING BORING



LOCATION PLAN



PROPOSED FLOOD CONTROL
CONDUIT & SIPHON SPILLWAYS
HERRING BROOK
PLEASANT STREET TO WHITMANS
WEYMOUTH

DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS
DIVISION OF WATERWAYS

M&E METCALF & EDDY, INC. ENGINEERS

OCTOBER, 1969

DESIGNED BY


TRACED BY

APPROVED BY

CONTRACT NO. 2664


ACC. NO. 047


DEPUTY CHIEF ENGINEER



STA.	DISTANCE	BEARING
A TO B	416.34	S 16-30 E
B TO C	336.44	S 65-00 W
C TO D	210.00	N 13-05 W
C TO C ₁	190.13	N 77-02 W
D TO E	70.00	N 51-40 W
E TO F	136.23	N 31-41 W
F TO A	180.82	S 73-00 E
D TO 100H	216.77	N 06-03 E
100H TO LOT	279.74	N 67-36-16 E


PLAN
SCALE: 1"=40'
SCALE IN FEET





LAN

0 40 80
FEET



10-12-70	JMTA	HPT	REMOVE PORTION OF 50' DRAIN
9-9-70	-E.R.E.-	HPT	EXTEND 50' ECA AND FISHWAY
REVISION	MADE BY	CHECKED BY	DESCRIPTION

PROPOSED FLOOD CONTROL
CONDUIT & SIPHON SPILLWAYS
HERRING BROOK
PLEASANT STREET TO WHITMANS POND
WEYMOUTH


IRON HILL DAM-SITE PLAN



DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS
DIVISION OF WATERWAYS

MIE METCALF & EDDY, INC. ENGINEERS
BOSTON - NEW YORK - PALM SPRING


OCTOBER, 1969
DESIGNED BY HPT
TRACED BY J.S.T.
APPROVED BY J.F.A.

CONTRACT NO. 2664 ACC. NO. 04762-C



CONTINUATION
SHEET 3PLAN
SCALE: 1"=10'* TO BE VERIFIED BY CONTRACTOR
IN THE FIELD.


PLAN



SECTION

DETAIL A

SCALE: 1/4"=1'-0"



SECTION

SCALE: 1/4"=1'-0"

REVISION	DATE	BY	CHECKED BY	DESCRIPTION
1	10-9-59	H.S.W.	HPT	EXTEND SET WA
2	10-9-59	H.S.W.	HPT	ADD F.I.S. - HPT

PROPOSED FLOOD CONTROL
CONDUIT & SIPHON SPILLWAYS
HERRING BROOK
PLEASANT STREET TO WHITMANS POND
WEYMOUTH

IRON HILL DAM-PLAN AND DETAILS

DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS
DIVISION OF WATERWAYS

ME METCALE & EDDY, INC. ENGINEERS
SECTION - 100-1000 - 100-1000

OCTOBER, 1959

DESIGNED BY HPT


BY REVIEW DATE


TRACED BY J.E.B.

APPROVED BY V.E.A.

CONTRACT NO. 2664 ACC. NO. 04762


8-40







PROPOSED FLOOD CONTROL CONDUIT & SIPHON SPILLWAYS HERRING BROOK PLEASANT STREET TO WHITMAN'S POND WEYMOUTH	
IRON HILL DAM - CONDUIT-PROFILE	
DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS DIVISION OF WATERWAYS	
ME METEEL & EBBY, INC. ENGINEERS BOSTON NEW YORK FALLS CHICAGO	
OCTOBER, 1969 DAY REVIEW BY <u>222</u> DATE <u>2/28</u>	DESIGNED BY <u>NP</u> TRACED BY <u>NP</u> APPROVED BY <u>NP</u>
CONTRACT NO. 2664 ACC. NO. 04762-E	

2484-B






SECTION 22
SCALE: $\frac{3}{8}$ " = 1'-0"




DETAIL C
SCALE: $1\frac{1}{2}$ " = 1'-0"
(TYP. CREST DETAIL)




DETAIL D
SCALE: $1\frac{1}{2}$ " = 1'-0"


PROPOSED FLOOD CONTROL CONDUIT & SIPHON SPILLWAYS		
HERRING BROOK		
PLEASANT STREET TO WHITMANS POND WEYMOUTH		
WHITMANS POND-SECTIONS I		
DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS DIVISION OF WATERWAYS		
M&E CONSULTANTS & ENGINEERS, INC. ENGINEERS BOSTON NEW YORK WASHINGTON FIELD OFFICE		
OCTOBER, 1969	DESIGNED BY <u>27</u>	
BY <u>27</u> REVIEW	TRACED BY <u>446</u>	
DATE <u>10/14/69</u>	APPROVED BY <u>KSA</u>	
CONTRACT NO. 2664 ACC. NO. 04762-G		



SECTION 1
SCALE: 3/8" = 1'-0"




SECTION 2
SCALE: 3/8" = 1'-0"




SECTION 3
SCALE: 1/4" = 1'-0"


NOTE: FOR DETAILS OF TRASH & WOOD BAPPLES SEE 1



SECTION 3
SCALE: 3/8" = 1'-0"




NOTE: FOR DETAILS OF TRASH RACK & WOOD BAFFLES SEE SH 12




SECTION 5
SCALE: 3/8" = 1'-0"

REVISION	DATE	BY	MADE BY	CHECKED BY	DESCRIPTION
1	9-2-70	R.H.S.	MPT		CHANGE WOOD BAFFLE TO DET C
2	4-29-70	D.J.	R.H.S.		ADDED SECT 3, REV SECT 5


PROPOSED FLOOD CONTROL CONDUIT & SIPHON SPILLWAYS HERRING BROOK PLEASANT STREET TO WHITMANS POND WEYMOUTH	
WHITMANS POND-SECTIONS II	
DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS DIVISION OF WATERWAYS	
M.E. MAYCALP & SODDY, INC. ENGINEERS <small>2007200 NEW YORK FIELD ALICE</small>	
OCTOBER, 1969 DESIGNED BY <u>RV</u> D.P.W. REVIEW DATE <u>10-1-69</u> TRACED BY <u>RV</u> APPROVED BY <u>RV</u>	CONTRACT NO. 2664 ACC. NO. 04762-H





PART PLAN

SCALE: 1/4" = 1'-0"



SECTION

NO SCALE

REVISION	DATE	BY	CHKD BY	DESCRIPTION
1	10-1-10	D.J.T.	HPT	ADDED RETAINING WALL
2	10-9-10	H.N.C.	HPT	ADDED PAVEMENT

HERRING BROOK
PLEASANT STREET TO WHITMANS POND
WEYMOUTH

IRON HILL DAM - PLAN


DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS
DIVISION OF WATERWAYS

M.E. HESTON & SONS, INC. ENGINEERS

OCTOBER, 1909
DESIGNED BY J.V.
TRACED BY J.L.J.
APPROVED BY M.C.C.

CONTRACT NO. 2664 ACC. NO. 04762-M

2 - VERIFY DIMENSION IN FIELD.



✓ L.J. 3-3 (ALUM)
(2 SIDES OF OPG)




1" BENT & W/ 1" x 1/2" x 1'-0"
ANCH. STRAPS @ 16" O.C.
(ALUM.)

SCALE : 1" = 1'-0"


DATE 12/11/51 APPROVED BY _____	
CONTRACT NO. 2664	ACC. NO. 0



SECT
SCALE: 1"




PROPOSED FLOOD CONTROL CONDUIT & SIPHON SPILLWAYS	
HERRING BROOK	
PLEASANT STREET TO WHITMANS PO WEYMOUTH	
IRON HILL DAM-SECTIONS II	
DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS DIVISION OF WATERWAYS	
M.E. METCALF & EDDY, INC. ENGINEERS BOSTON - NEW YORK - CHICAGO	
OCTOBER, 1969	DESIGNED BY
BY	TRACED BY
DATE	APPROVED BY
CONTRACT NO. 2664 / ACC. NO. 0476	



CROSS SECTION THRU PRESSURE CONDUIT



SCALE: 1/4" = 1'-0"

NOTE: THE CONDUIT SHALL BE CONSTRUCTED TO MINIMIZE THE EFFECT OF CONCRETE SHRINKAGE BY PLACING ALTERNATE SECTIONS IN CHECKERBOARD STYLE. SUFFICIENT CURING TIME FOR INITIAL CONCRETE SHRINKAGE SHALL BE ALLOWED BEFORE PLACING ALTERNATE SECTIONS. THE DISTANCE BETWEEN CONSTRUCTION JOINTS SHALL NOT EXCEED 30'-0" AND BETWEEN EXPANSION JOINTS SHALL NOT EXCEED 70'-0". FOR JOINT DETAILS SEE SHEET 10. ANY ROCK BELOW FOM. MAT SHALL BE REMOVED 1'-0" MIN. AND BACK-FILLED WITH BANK RUN GRAVEL COMPACTED TO 95% OF DENSITY.




<p>PROPOSED FLOOD CONTROL CONDUIT & SIPHON SPILLWAYS</p> <p>HERRING BROOK</p> <p>PLEASANT STREET TO WHITMANS POND WEYMOUTH</p>	
<p>IRON HILL DAM - CONDUIT SECTIONS</p>	
<p>DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETT DIVISION OF WATERWAYS</p>	
<p>M.E. METCALF & EDDY, INC. ENGINEERS 02122 - NEW YORK - 10020 - 1000 0170</p>	
<p>OCTOBER, 1969 DESIGNED BY BY <i>[Signature]</i> DATE 10/1/69</p>	<p>TRACED BY <i>[Signature]</i> APPROVED BY <i>[Signature]</i></p>
<p>CONTRACT NO. 2664 ACC. NO. 04762-</p>	


2484-B



PROPOSED FLOOD CONTROL CONDUIT & SIPHON SPILLWAYS	
HERRING BROOK	
PLEASANT STREET TO WHITMANS WEYMOUTH	
WHITMANS POND-BRIDGE PLAN & E	
DEPARTMENT OF PUBLIC WORKS OF MASSA DIVISION OF WATERWAYS	
M&E METCAL & EDDY, INC. ENGINEERS BOSTON - NEW YORK - PALM BEACH	
OCTOBER, 1969	DESIGNED BY
BY J. W. REVIEW	TRACED BY
DATE 10/1/69	APPROVED BY
CONTRACT NO 2664 ACC. NO. 04	




PLAN-SECTION (17)
SCALE: $\frac{1}{8}" = 1'-0"$



PLAN-SECTION (18)
SCALE: $\frac{1}{8}" = 1'-0"$

FOR DECK ANCHORS—
SEE BEARING DET. TH. SH



**BEARING DETAIL
AT ABUTMENT**
SCALE: $\frac{1}{8}" = 1'-0"$




**BEARING DETAIL
AT PIER**
SCALE: $\frac{1}{8}" = 1'-0"$

BRIDGE ELEV. ARE
GIVEN ON THIS LINE
(SEE SH. 18)


4" DIA. PIPE SLEEVE
SCUPPERS, 2 @ SPAN
@ LOW POINTS.

NOTES FOR PRESTRESSED CONCRETE BEAMS

1. SPECIFICATIONS: "AASHTO STANDARD SPECIFICATION FOR HIGHWAY BRIDGES, CURRENT EDITION: 'CRITERIA FOR PRESTRESSED CONCRETE BRIDGES, U.S. BUREAU OF PUBLIC ROADS', AASHTO STANDARD BUILDING CODE REQUIREMENTS FOR REINFORCED CONCRETE (ACI 318-63), 1963 EDITION; AND ANY SUBSEQUENT REVISIONS APPROVED BY THE COMMISSION ON BRIDGES AND STRUCTURES OF AASHTO.
2. LIVE LOADS: A UNIFORMLY DISTRIBUTED LOAD OF 100 P.S.F. ON AN ENTIRE AREA.
3. SUBSTITUTION: SIMILAR BEAM SECTIONS WITH MINOR DIMENSIONAL VARIATIONS, MANUFACTURED WITH ESTABLISHED PLANT FACILITIES WHICH MEET STRUCTURAL AND GEOMETRICAL REQUIREMENTS OF THIS PROJECT, MAY BE SUBSTITUTED UPON SUBMISSION BY THE PRODUCER OF THE DATA NECESSARY TO SHOW COMPLIANCE WITH THE REQUIREMENTS OF THE JOB AND UPON APPROVAL OF THE SUBSTITUTION BY THE ENGINEER.
4. CONCRETE: 28-DAY STRENGTH OF CONCRETE, $f'_c = 5,000$ P.S.I.; AND STRENGTH OF CONCRETE AT THE TIME OF TRANSFER OF STRESS, $f'_c = 4,000$ P.S.I.
5. PRESTRESSING REINFORCEMENT: MATERIALS FOR PRESTRESSING REINFORCEMENT SHALL BE ANY OF THE MATERIALS SPECIFIED IN THE GOVERNING SPECIFICATIONS.
6. END BLOCKS: SUFFICIENT MILD STEEL REINFORCEMENT SHALL BE PROVIDED IN END BLOCKS TO RESIST THE TENSILE FORCES DUE TO CONCENTRATED PRESTRESSING LOADS.
7. DIAPHRAGMS: DIAPHRAGMS CAST WITHIN THE BEAM SHALL BE LOCATED AT THE THIRD POINTS OF THE SPAN.
8. LATERAL TIES: LATERAL TIES SHALL BE PROVIDED THROUGH THE BEAM AND BEAM ENDS AS REQUIRED: EACH TIE SHALL BE EQUIVALENT TO A MILD STEEL BAR TENSIONED TO 12,000 POUNDS OR AN EQUAL FORCE BY LATERAL TENSIONING OF HIGH STRENGTH TENDONS. TENSIONING SHALL TAKE PLACE AFTER NON-SHRINKING GROUT IN LONGITUDINAL WALL HAS HARDENED FOR AT LEAST 3 DAYS.
9. CHAMFERS AND CORNERS: ALL EXPOSED CORNERS SHALL BE CHAMFERED $\frac{3}{4}$ " OR ROUNDED TO $\frac{3}{4}$ " RADIUS.
10. FINISH: TOPS SHALL BE GIVEN A BROOM FINISH, NORMAL TO CENTER OF ROADWAY.
11. HANDLING: IN HANDLING, THE BEAMS MUST BE MAINTAINED IN POSITION AT ALL TIMES AND MUST BE PICKED UP ONLY BY MEANS OF APPROVED DEVICES NEAR THE ENDS OF THE BEAMS.
12. SHOP DRAWINGS: SHOP DRAWINGS AND DESIGN COMPUTATIONS, SHOWING DETAILS OF CONSTRUCTION AND ERECTION SHALL BE SUBMITTED TO ENGINEER IN QUADRUPPLICATE FOR APPROVAL BEFORE FABRICATION.
13. WEIGHTS: WEIGHTS OF BEAMS SHALL BE PLAINLY PRINTED ON STEEL ON EACH MEMBER.



NOTE: REINF AND PRESTRESSING STRANDS NOT SHOWN.



PROPOSED FLOOD CONTROL CONDUIT & SIPHON SPILLWAYS	
HERRING BROOK	
PLEASANT STREET TO WHITMANS POND WEYMOUTH	
WHITMANS POND - BRIDGE SECTION	
DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS DIVISION OF WATERWAYS	
M.E. METCALF & GORDY, INC. ENGINEERS BOSTON NEW YORK CHICAGO	
OCTOBER, 1969	DESIGNED BY
BY <i>EC</i> REVIEW	TRACED BY <i>EC</i>
DATE <i>10/1/69</i>	APPROVED BY <i>EC</i>
CONTRACT NO. 2664 ACC. NO. 0476	

BORING NO. 8-1 GROUND ELEV. 73.4 DATE: 2/69

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN/FT	SOIL IDENTIFICATION	SAMPLE NO.
0			2" OF FROST	
5	13		BROWN FINE TO COARSE SAND, WOOD, GRAVEL, FILL	1 2'-3'-6" REC 12"
10	17		10' TO 11' CORED BOULDER	2 5'-6'-6" REC 12"
13'-0"			TOP OF ROCK 13'-0"	
15		7	PINK GRANITE VERY HARD SEAMY	C-1 13'-17" REC 43"
20		12		C-2 17'-20" REC 33"
25		10	GRAY GRANITE SOME TRAP ROCK VERY SEAMY	C-3 20'-25" REC 22"
		12		
		7		
		8		
		7	HARD	

BOTTOM OF BORING 25'-0"

NOTES:

1. WATER LEVEL AT 6' AFTER 1 HOUR.
2. 1 3/8" ROCK CORE.

BORING NO. 8-2 GROUND ELEV. 70.8 DATE: 2/69

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN/FT	SOIL IDENTIFICATION	SAMPLE NO.
0			1" OF FROST	
5	12		BROWN FINE SAND, WOOD, AND GRAVEL FILL	1 1'-2'-6" REC 12"
7'-0"	18		TOP OF ROCK 7'-0"	2 5'-6'-6" REC 12"
10		6	PINK GRANITE VERY SEAMY MEDIUM HARD	C-1 7'-12" REC 14"
15		5		C-2 12'-14'-6" REC 22"
		7		C-3 14'-6"-19'-6" REC 60"
		8		
		5		
		7	8 15' BECOMES VERY HARD	
		16		C-4 19'-6"-23" REC 42"
		17		
		19		
		21		
		16		
		18		
23'-0"		27		

BOTTOM OF BORING 23'-0"

NOTES:

1. WATER LEVEL AT 2' AFTER 1 HOUR.
2. 2" ROCK CORE.

BORING NO. 8-3 GROUND ELEV. 74

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN/FT	SOIL IDENTIFICATION
0			2" OF FROST
5	22		BROWN FINE SAND, COARSE GRAVEL, FILL
8'-0"	28		TOP OF ROCK 8'-0"
10		13	PINK GRANITE VERY SEAMY
15		14	
		16	
		20	
		24	
		11	
		12	
		19	
		21	
		16	
		21	
		20	
		31	
		26	
		11	
		14	
		12	
		14	
28'-0"		16	

BOTTOM OF BORING 28'-0"

NOTES:

1. WATER LEVEL AT 7' AFTER 2 HOURS.
2. 2" ROCK CORE.

BORING NO. 8-6 GROUND EL. 70.9 DATE: 3/69

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN/FT	SOIL IDENTIFICATION	SAMPLE NO.
0	2		BROWN COARSE TO FINE SAND AND GRAVEL, LITTLE SILT, FILL	1 0'-1'-6" REC 10"
5	2			2 5'-6'-6" REC 12"
9'-0"			TOP OF ROCK 9'-0"	
10		3	PINK GRANITE SEAMY AND HARD	C-1 9'-14" REC 56"
15		3		
		4		
		5	8" SEAM OF TRAP ROCK @ 13'	C-2 14'-19" REC 56"
		10		
		15		
19'-0"		20		

BOTTOM OF BORING 19'-0"

NOTES:

1. WATER LEVEL AT 3'-0" AFTER 3 HOURS.
2. 8X ROCK CORE.

BORING NO. 8-7 GROUND ELEV. 74.8 DATE: 2/69

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN/FT	SOIL IDENTIFICATION	SAMPLE NO.
0	12		BROWN COARSE TO FINE SAND & COARSE TO FINE GRAVEL (LOST SPLIT SPUR IN HOLE - NO SAMPLE)	
5'-6"			TOP OF ROCK 5'-6"	
10		4	PINK GRANITE	C-1 5'-6"-10'-6" REC 43"
		5		
		4		
		2	TILL SEAM FROM 9'-6" TO 11'-0" THEN BACK TO GRANITE	
		6		1 C-2 11'-15" REC 43"
		8		
15'-0"		10		
		15		

BOTTOM OF BORING 15'-0"

NOTES:

1. HOLE CAVED IN AT 5' (NO WATER READINGS).
2. 4X ROCK CORE.

BORING NO. 8-9 GROUND ELEV. 60.4

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN/FT	SOIL IDENTIFICATION
0	5		BROWN COAR SAND & COA GRAVEL, L.
5		4	TOP OF ROCK
		5	
		7	PINK GRANITE
		4	WEATHERED
		5	VERTICAL S
10		5	(CORE BARR
		4	KEPT JAWN
		5	
		5	
		5	
		5	
		8	
		10	
		15	
		19	
		3	
		4	
25'-0"		7	
		15	

BOTTOM OF BORING 25'-0"

NOTES:

1. WATER LEVEL AT 18'-0" FROM GROUND LEVEL
2. 1 3/8" ROCK CORE

BORING NO. B-3 GROUND ELEV. 74.4 DATE 2-69

DEPTH	SAMPLER BLOWS FT	CORE RATE	SOIL IDENTIFICATION	SAMPLE NO.
0'-0"			2' OF FROST	
2'-0"	22		BROWN FINE TO COARSE SAND AND GRAVEL, COBBLES, FILL	2'-3'-6" REC 12
4'-0"	28		TOP OF ROCK 8'-0"	5'-8'-6" REC 16
6'-0"			PINK GRANITE VERY SEAMY HARD	C-1 8'-13" REC 12
8'-0"				C-2 13'-18" REC 47
10'-0"				C-3 18'-23" REC 59
12'-0"				C-4 23'-28" REC 30
14'-0"				
16'-0"				
18'-0"				
20'-0"				
22'-0"				
24'-0"				
26'-0"				
28'-0"				
30'-0"				
32'-0"				
34'-0"				
36'-0"				
38'-0"				
40'-0"				
42'-0"				
44'-0"				
46'-0"				
48'-0"				
50'-0"				
52'-0"				
54'-0"				
56'-0"				
58'-0"				
60'-0"				
62'-0"				
64'-0"				
66'-0"				
68'-0"				
70'-0"				
72'-0"				
74'-0"				
76'-0"				
78'-0"				
80'-0"				
82'-0"				
84'-0"				
86'-0"				
88'-0"				
90'-0"				
92'-0"				
94'-0"				
96'-0"				
98'-0"				
100'-0"				

BOTTOM OF BORING 28'-0"

NOTES:

1. WATER LEVEL AT 7' AFTER 2 HOURS.
2. ROCK CORE.

BORING NO. B-4 GROUND ELEV. 50.4 DATE 2-69

DEPTH	SAMPLER BLOWS FT	CORE RATE	SOIL IDENTIFICATION	SAMPLE NO.
0'-0"			GRAY, BROWN WEATHERED ROCK WITH COARSE SAND AND GRAVEL	0'-1'-6" REC 18
2'-0"	91		TOP OF ROCK 2'-0"	
4'-0"			PINK GRANITE SEAMY AND HARD VERTICAL SEAMS	C-1 3'-8" REC 60
6'-0"				C-2 8'-11'-6" REC 42
8'-0"				C-3 11'-6"-15'-6" REC 60
10'-0"				
12'-0"				
14'-0"				
16'-0"				
18'-0"				
20'-0"				
22'-0"				
24'-0"				
26'-0"				
28'-0"				
30'-0"				
32'-0"				
34'-0"				
36'-0"				
38'-0"				
40'-0"				
42'-0"				
44'-0"				
46'-0"				
48'-0"				
50'-0"				
52'-0"				
54'-0"				
56'-0"				
58'-0"				
60'-0"				
62'-0"				
64'-0"				
66'-0"				
68'-0"				
70'-0"				
72'-0"				
74'-0"				
76'-0"				
78'-0"				
80'-0"				
82'-0"				
84'-0"				
86'-0"				
88'-0"				
90'-0"				
92'-0"				
94'-0"				
96'-0"				
98'-0"				
100'-0"				

BOTTOM OF BORING 16'-6"

NOTES:

1. WATER LEVEL AT -3'-3" FROM GROUND LEVEL
2. LOST WATER AT 6'
3. 1 1/2" ROCK CORE

BORING NO. B-5 GROUND ELEV. 73.0 DATE 3-69

DEPTH	SAMPLER BLOWS FT	CORE RATE	SOIL IDENTIFICATION	SAMPLE NO.
0'-0"			BROWN LOAN FOR 6' TO BROWN FINE TO COARSE	
2'-0"	9			
4'-0"			BROWN COARSE TO FINE SAND AND COARSE TO FINE GRAVEL, LITTLE SILT	
6'-0"	37			
8'-0"			TOP OF ROCK 10'-0"	
10'-0"			PINK GRANITE SEAMY	
12'-0"				
14'-0"				
16'-0"				
18'-0"				
20'-0"				
22'-0"				
24'-0"				
26'-0"				
28'-0"				
30'-0"				
32'-0"				
34'-0"				
36'-0"				
38'-0"				
40'-0"				
42'-0"				
44'-0"				
46'-0"				
48'-0"				
50'-0"				
52'-0"				
54'-0"				
56'-0"				
58'-0"				
60'-0"				
62'-0"				
64'-0"				
66'-0"				
68'-0"				
70'-0"				
72'-0"				
74'-0"				
76'-0"				
78'-0"				
80'-0"				
82'-0"				
84'-0"				
86'-0"				
88'-0"				
90'-0"				
92'-0"				
94'-0"				
96'-0"				
98'-0"				
100'-0"				

BOTTOM OF BORING 15'-0"

SAND, LITTLE FINE TO MED JM GRAVEL, TRACE OF SILT

NOTES:

1. WATER LEVEL AT 5' AFTER 1 1/2 HOUR
2. 1 1/2" ROCK CORE

BORING NOTES

1. TEST BORINGS WERE MADE BY C.L. GUILD DRILLING & BORING CO., INC. BRAintree, MASSACHUSETTS DURING FEBRUARY, MARCH, AND JUNE OF 1969.
2. THE BORING LOGS SHOWN HAVE BEEN REPRODUCED FROM THE ORIGINAL LOGS PREPARED BY C.L. GUILD.
3. THE ORIGINAL BORING LOGS, THE SOIL SAMPLES AND THE ROCK CORES SEEN AT THE DEPARTMENT OF PUBLIC WORKS, DIVISION OF WATERWAYS REQUEST.
4. SAMPLER BLOW COUNT WAS MEASURED ON A 1 1/2" SPLIT SPOON SAMPLE A 140 LB. HAMMER AND A 30" FALL. ROCK CORES WERE MADE WITH A BITS OF THE SIZES INDICATED.
5. PREVIOUS BORINGS WERE MADE ALONG THE CONDUIT AND IN FRENCH HILL THEIR APPROXIMATE LOCATION IS SHOWN ON SHEET 3 (INDICATED) AND INFORMATION MAY BE OBTAINED FROM THE DIVISION OF WATERWAYS.
6. THE ENGINEER DOES NOT GUARANTEE THE ACCURACY OF THE BORING LOGS.

BORING NO. B-9 GROUND ELEV. 60.4 DATE 2-69

DEPTH	SAMPLER BLOWS FT	CORE RATE	SOIL IDENTIFICATION	SAMPLE NO.
0'-0"			BROWN COARSE TO FINE SAND & COARSE TO FINE GRAVEL, LITTLE SILT	0'-1'-6" REC 18
2'-0"	5		TOP OF ROCK 3'-0"	C-1 3'-7" REC 41
4'-0"			PINK GRANITE WEATHERED AND SEAMY VERTICAL SEAMS	C-2 7'-11" REC 26
6'-0"			(CORE BARREL KEPT JAMMING UP)	C-3 11'-16" REC 32
8'-0"				C-4 16'-21" REC 21 1/2
10'-0"				
12'-0"				
14'-0"				
16'-0"				
18'-0"				
20'-0"				
22'-0"				
24'-0"				
26'-0"				
28'-0"				
30'-0"				
32'-0"				
34'-0"				
36'-0"				
38'-0"				
40'-0"				
42'-0"				
44'-0"				
46'-0"				
48'-0"				
50'-0"				
52'-0"				
54'-0"				
56'-0"				
58'-0"				
60'-0"				
62'-0"				
64'-0"				
66'-0"				
68'-0"				
70'-0"				
72'-0"				
74'-0"				
76'-0"				
78'-0"				
80'-0"				
82'-0"				
84'-0"				
86'-0"				
88'-0"				
90'-0"				
92'-0"				
94'-0"				
96'-0"				
98'-0"				
100'-0"				

BOTTOM OF BORING 25'-0"

NOTES:

1. WATER LEVEL AT -3'-2" FROM GROUND LEVEL
2. 1 1/2" ROCK CORE

BORING NO. B-10 GROUND ELEV. 58.6 DATE 2-69

DEPTH	SAMPLER BLOWS FT	CORE RATE	SOIL IDENTIFICATION	SAMPLE NO.
0'-0"			BROWN, COARSE TO FINE SAND & COARSE TO FINE GRAVEL, LITTLE SILT	0'-1'-6" REC 12
2'-0"	6		TOP OF ROCK 3'-5"	
4'-0"			PINK GRANITE WEATHERED AND SEAMY	C-1 3'-8" REC 7
6'-0"			GOOD ROCK FROM 7'-8"	C-2 5'-8" REC 21
8'-0"				C-3 7'-8" REC 24
10'-0"				C-4 10'-15" REC 60
12'-0"				
14'-0"				
16'-0"				
18'-0"				
20'-0"				
22'-0"				
24'-0"				
26'-0"				
28'-0"				
30'-0"				
32'-0"				
34'-0"				
36'-0"				
38'-0"				
40'-0"				
42'-0"				
44'-0"				
46'-0"				
48'-0"				
50'-0"				
52'-0"				
54'-0"				
56'-0"				
58'-0"				
60'-0"				
62'-0"				
64'-0"				
66'-0"				
68'-0"				
70'-0"				
72'-0"				
74'-0"				
76'-0"				
78'-0"				
80'-0"				
82'-0"				
84'-0"				
86'-0"				
88'-0"				
90'-0"				
92'-0"				
94'-0"				
96'-0"				
98'-0"				
100'-0"				

BOTTOM OF BORING 15'-0"

NOTES:

1. WATER LEVEL AT -4'-11" FROM GROUND LEVEL
2. 1 1/2" ROCK CORE

PROPOSED FLOOD CONTROL
CONDUIT & SIPHON SPILLWAYS
HERRING BROOK
PLEASANT STREET TO WHITMAN
WEYMOUTH

BORING LOGS I

DEPARTMENT OF PUBLIC WORKS OF MASS
DIVISION OF WATERWAYSME GUSTAF & SONS, INC. ENGINEER
BOSTON NEW YORK PALM BEACHOCTOBER, 1969 DESIGNED BY
DPW REVIEW TRACED BY
BY DATE 10/14/69 APPROVED BY

CONTRACT NO. 2664 ACC. NO. C

BORING NO. B-11 GROUND ELEV. 61.1 DATE: 2 69

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN. FT.	SOIL IDENTIFICATION	SAMPLE NO.
0	2		BROWN FINE TO COARSE SAND, SOME COARSE TO FINE GRAVEL, LITTLE SILT	0-1'-6" REC 12"
5		6 10 20 26 4		C-1 3'-6"-8'-6" REC 58 1/2"
10		7 12 5/8" 20 5/8" 3 5/8"		C-2 8'-6"-11' REC 28"
15		9 8 9 13 15 20 1/2		C-3 11'-6"-16' REC 54"
20		8 12 15 25		C-5** C-6 17'-2"-22'-2" REC 57 1/2"
22'-2"				

BOTTOM OF BORING 22'-2"

NOTES:

1. CHANGED BITS AT 8'-6", 11'-6" AND AT 17'-2".
2. WATER LEVEL AT 4'-6" FROM GROUND LEVEL
3. 1 3/8" ROCK CORE.

**C-3 11'-11'-6" REC. 4"

**C-5 16'-17'-2" REC. 16"

BORING NO. B-12 GROUND ELEV. 72.5 DATE: 2 69

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN. FT.	SOIL IDENTIFICATION	SAMPLE NO.
0			1'-6" OF FROST	
5	13	11 1/6"	BROWN FINE SAND, WOOD AND GRAVEL, FILL	2'-3'-8" REC 12"
10		6 7 8 13 10 16 10 19	BROWN FINE SAND & FINE GR. PINK GRANITE AND TRAP ROCK VERY BEAMY MEDIUM HARD	C-1 5'-10' REC 37"
15		11 12 16 10 19	PINK GRANITE NOT TOO BEAMY HARD	C-2 10'-15' REC. 44"
20		11 12 16 14 21	PINK GRANITE & TRAP ROCK VERY HARD	C-3 15'-20' REC. 60"
20'-0"				

BOTTOM OF BORING 20'-0"

NOTES:

1. WATER LEVEL AT 9' AFTER 1 1/2 HOUR.
2. 1 3/8" ROCK CORE

**2'-4'-5' REC. 9"

BORING NO. B-18 GROUND ELEV. 66 0

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN. FT.	SOIL IDENTIFICATION	SAMPLE NO.
0			2' OF FROST	
5	51		BROWN FINE TO MEDIUM SAND, LITTLE FINE GRAVEL, FILL	
10	16		BROWN FINE TO MEDIUM SAND LITTLE FINE GRAVEL, FILL	
15		21	GRAY FINE TO MEDIUM SAND, LITTLE SILT & FINE TO MEDIUM GRAVEL, TRACE COARSE SAND	
20		31		
25		14	BROWN FINE TO COARSE SAND, LITTLE FINE TO COARSE GRAVEL, COBBLE	
30		6 11 12 14 16 13 16 14 15 21	PINK GRANITE VERY HARD	
35				

BOTTOM OF BORING 35'-7"

NOTES:

1. 25' TO 25'-7" RUNNING SAND
2. WATER LEVEL AT 6'-4", 2/14/69
3. 2" ROCK CORE

BORING NO. B-21 GROUND ELEV. 65.4 DATE: 3 69

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN. FT.	SOIL IDENTIFICATION	SAMPLE NO.
0	21		1' OF FROST	
5	21		BROWN FINE SAND, LITTLE FINE GRAVEL, FILL	2'-3'-6" REC 12"
10		10 20 22 24 26 6 7	WHITE GRANITE VERY HARD	C-1 5'-6"-10'-6" REC 54"
15		26 6 7 20 20 27	10'-6" TO 11'-6" VERY BEAMY	C-2 10'-6"-15'-6" REC 30"
15'-6"				

BOTTOM OF BORING 15'-6"

NOTES:

1. WATER LEVEL AT 3'-4" AFTER 2 HOURS
2. 1 3/8" ROCK CORE.

**2. 0'-8'-8" REC 12"

BORING NO. B-22 GROUND ELEV. 57.6 DATE: 3 69

DEPTH	SAMPLER BLOWS FT.	CORE RATE MIN. FT.	SOIL IDENTIFICATION	SAMPLE NO.
0			2' OF FROST	
5	16		BLACK COAL & ASHES, FILL	2'-3'-8" REC 12"
10	20		BROWN FINE SAND, TRACE OF FINE GRAVEL	2' 3"
15	25		BROWN FINE SAND, LITTLE FINE GRAVEL, TRACE OF SILT	5'-9'-6" REC 12"
20	31		BROWN FINE TO COARSE SAND, TRACE OF SILT	5***
25	30		BROWN FINE SAND, TRACE OF SILT	6***
30		6 9 12 18 20	PINK GRANITE VERY HARD - FEW SEAMS	C-1 12'-10' REC 52"
30'-0"				

BOTTOM OF BORING 30'-0"

NOTES:

1. WATER LEVEL AT 12' AFTER 1 HOUR

2. 2" ROCK CORE

**2. 0'-8'-8" REC. 12"

**3. 0'-8'-8" REC. 12"

***6. 10'-11'-6" REC. 12"

****6. 11'-8'-18" REC. 1"

BORING NO. B-23 GROUND ELEV. 65.4

DEPTH	SOIL IDENTIFICATION	SAMPLE NO.
0	BROWN	
5	FINE TO MEDIUM SAND SOME COARSE GRAVEL	
10		
15		
20	COARSE ROCK RUN NO. 1 RECOVERY 42"	
25		

BOTTOM OF BORING 25'-6"

NOTE: AFTER BORING

GROUND ELEV. 66.0 DATE: 2 69

CORE RATE	SOIL IDENTIFICATION	SAMPLE NO.
	2' OF FROST	
	BROWN FINE TO MEDIUM SAND, LITTLE FINE GRAVEL, FILL	1 2'-3'6" REC 12"
	BROWN FINE TO MEDIUM SAND	2 5'-6'6" REC 12"
	LITTLE FINE GRAVEL, FILL	
		3 10'-11'6" REC 12"
	GRAY FINE TO MEDIUM SAND, LITTLE SILT & FINE TO MEDIUM GRAVEL, TRACE OF COARSE SAND	4 15'-17'5" REC 11"
		5 120'-21'-6" REC 12"
	BROWN FINE TO COARSE SAND, LITTLE FINE TO COARSE GRAVEL, COBBLES	6 23'-6"-25' REC 12"
	PINK GRANITE VERY HARD	C-1 25'-7"-33'7" REC 60"
		C-2 30'-7"-35'7" REC 59"

BOTTOM OF BORING 35'-7"

BORING SAND
1'-0", 2/14/69

BORING NO. B-19 GROUND ELEV. 65.5 DATE: 2 69

DEPTH	SAMPLER BLOWS FT	CORE RATE	SOIL IDENTIFICATION	SAMPLE NO.
0			2' OF FROST	
2'-0"	70			
5	30		BROWN FINE TO COARSE SAND, LITTLE FINE TO MED. GRAVEL, SMALL COBBLES	1 2'-3'6" REC 12"
				2 5'-6'6" REC 12"
10			TOP OF ROCK 10'-5"	
15		6	WHITE GRANITE VERY SEMI MEDIUM HARD	C-1 10'-5"-15'5" REC 40"
		11		
		12		
		13		
		14		
		8		
		10		
		12		
		13		
		10		
		14		
		15		
		15		
25	25'-5"			C-2 15'-5"-20'5" REC 89"
				C-3 20'5"-25'5" REC 60"

BOTTOM OF BORING 25'-5"

NOTES:

1. LOST WATER AT 11'-6".
2. 2" ROCK CORE.

BORING NO. B-20 GROUND ELEV. 57.0 DATE: 2 69

DEPTH	SAMPLER BLOWS FT	CORE RATE	SOIL IDENTIFICATION	SAMPLE NO.
0			2' OF FROST	
2'-0"	21			
5	22		BROWN FINE TO COARSE SAND, LITTLE FINE TO MEDIUM GRAVEL, FILL	1 2'-3'6" REC 12"
				2 5'-6'6" REC 12"
10	16			
15			TOP OF ROCK 15'-0"	
		11	PINK GRANITE VERY HARD	C-1 15'-20' REC 58"
		16		
		17		
		21		
		25		
		26		
		19		
		21		
		25		
25	25'-0"			C-2 20'-25' REC 59"

BOTTOM OF BORING 25'-0"

NOTES:

1. LOST WATER AT 15'.
2. WATER LEVEL AT 14'. 2/14/69.
3. 2" ROCK CORE.

GROUND ELEV. 65.4 DATE: 6 69

SOIL IDENTIFICATION
BROWN
FINE TO MEDIUM SAND SOME COARSE GRAVEL
CORED ROCK RUN NO. 1 RECOVERY 42"

BOTTOM OF BORING 25'-0"

BORING NO. B-24 GROUND ELEV. 65.2 DATE: 6 69

DEPTH	SOIL IDENTIFICATION
0	BROWN
5	
10	FINE TO MEDIUM SAND SOME COARSE GRAVEL
15	
18'-0"	
20	CORED ROCK RUN NO. 1 RECOVERY 34"
25	

BOTTOM OF BORING 25'-0"

NOTE: AUGER BORING

NOTE: FOR GENERAL TEST BORING NOTES SEE SHEET 21.

PROPOSED FLOOD CONTROL
CONDUIT & SIPHON SPILLWAYS
HERRING BROOK
PLEASANT STREET TO WHITMANS POND
WEYMOUTH

BORING LOGS II

DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS
DIVISION OF WATERWAYS

ME METCALF & EDDY, INC. ENGINEERS
BOSTON NEW YORK WASH DC

OCTOBER, 1969

DESIGNED BY

BY



TRACED BY

DATE


APPROVED BY

CONTRACT NO. 2664 ACC. NO. 04762-V

2484-R




PLAN
SCALE: 1/8" = 1'-0"






DETAIL
SCALE: 1/4" = 1'-0"

SECTION
SCALE: 1/8" = 1'-0"



SECTION
SCALE: 1/8" = 1'-0"




SECTION 10
SCALE: 1/8" = 1'-0"

SECTION 5
SCALE: 1/8" = 1'-0"

<p>PROPOSED FLOOD CONTROL CONDUIT & SIPHON SPILLWAYS HERRING BROOK PLEASANT STREET TO WHITMANS WEYMOUTH</p>			
<p>IRON HILL FISHWAY</p>			
<p>DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS DIVISION OF WATERWAYS</p>			
<p>ME CONSULTING & STUDY, INC. ENGINEERS 2001 N. 1ST ST. NEW YORK, N.Y. 10001</p>			
<p>DESIGNED BY: J.L.B. CHECKED BY: J.L.B. DATE: SEPTEMBER, 1970</p>	<p>APPROVED BY: J.L.B.</p>		
<p>CONTRACT NO. 2664 ACC. NO. 04</p>			

APPENDIX C
PHOTOGRAPHS



LOUIS BERGER & ASSOC., INC. WELLESLEY, MASS. ARCHITECT · ENGINEER		U.S. ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
WHITMANS POND DAM			
SKETCH PLAN SHOWING LOCATION & ORIENTATION OF PHOTOS			
STATE - MA			SCALE
			DATE

C-1

WHITMANS POND DAM



1. Downstream face of dam and right abutment



2. Downstream face of dam and left abutment

WHITMANS POND DAM



3. Erosion at left downstream training wall




4. Downstream face of siphon spillway structure and ogee overflow section

WHITMANS POND DAM



5. Displaced riprap and erosion downstream
of right training wall



6. Upstream end of fish ladder

WHITMANS POND DAM



7. Downstream end of fish ladder



8. Right training wall of the spillway
approach channel

WHITMANS POND DAM



9. Downstream face of dam from left abutment




10. View along crest of dam from left abutment

WHITMANS POND DAM



11. Downstream face of concrete ogee overflow section



12. Downstream end of siphon spillway structure (4 units)

WHITMANS POND DAM



13. Concrete ogee overflow section. Note sluiceway through lower right corner of overflow section.

APPENDIX D
HYDROLOGIC AND HYDRAULIC COMPUTATIONS

BY RF3 DATE 3-25-80 **LOUIS BERGER & ASSOCIATES INC.**

SHEET NO. 1 OF 1

CHKD. BY DATE INSPECTION OF DAM

PROJECT W-125

SUBJECT W-125 - 454

Find 3 in Area, May 1979: 1124.000

Area 1	Read #2	231.26	Read #3	42.84	Ave = 29.55
	" #1	1.71	" #2	31.26	
		<u>29.55</u>		<u>29.55</u>	

Area 2	Read #2	27.47	Read #3	58.25	Ave = 27.72
	" #1	2.75	" #2	30.47	
		<u>27.72</u>		<u>27.72</u>	

Area 3	Read #2	100.30	Read #3	131.32	Ave = 31.01
	" #1	61.29	" #2	100.21	
		<u>31.01</u>		<u>31.01</u>	

DRAINAGE AREA = 98.3 (0.423) = 12.67 sq mi = 8109 Acres

Reservoir Area, Elev. 66

Read #2	43.30	Read #3	42.15
" #1	41.20	" #2	43.30
	<u>2.10</u>		<u>2.06</u>

Reservoir Area = 2.08 x 91.83 = 191 Acres

Area Elev. 70

Read #2	48.33	Read #3	51.15
" #1	45.54	" #2	48.33
	<u>2.79</u>		<u>2.82</u>

Area Elev. 70 = 2.805 x 91.83 = 258 Acres

Area Elev. 80	Read #2	32.96	Read #3	38.00
	" #1	27.71	" #2	32.96
		<u>5.05</u>		<u>5.04</u>

Area Elev. 80 = 5.04 x 91.83 = 463 Acres

D-1

Copy available to DTIC does not
permit fully legible reproduction

BY RFZ DATE 6-15-80 **LOUIS BERGER & ASSOCIATES INC.** SHEET NO. _____ OF _____
CHKD. BY _____ DATE _____ PROJECT W-132
SUBJECT Weymouth Pond, PME 5000

Check Town of Weymouth, D.A. 1987, MAXIMUM DRAINAGE
DATED 11 MARCH, 1987, MAXIMUM DRAINAGE
FLOW OF 5,100 CFS AGAINST CURVE OF
ENVELOPE CURVE FOR
1/2 COASTAL AREA.

Using COE CURVE

$$\text{TOTAL AREA} = \frac{7750 \text{ ACRES}}{300 \text{ A/MI}^2} = 12.11 \text{ SQ MI}$$

DEDUCT WEYMOUTH GREAT POND D.A. OF 2.82 SQ MI

DEDUCT 1/2 OLD SWAMP DRAIN SWAMP D.A. OF 1.75 SQ MI

$$\text{NET D.A.} = 7.47 \text{ SQ MI}$$

FROM ENVELOPE CURVE FOR D.A. = 7.47

$$\text{MPE IN CFS / SQ MI} = 750 \text{ CFS / SQ MI}$$

$$Q = \text{D.A.} \times 750 = 7.47 \times 750 = 5600 \approx 5100$$

USE TOWN OF WEYMOUTH HYDROLOGICAL FOR
ROUTING & PME = 5100 CFS

Copy available to DTIC does not
permit fully legible reproduction

BY RFE DATE 6-15-80 **LOUIS BERGER & ASSOCIATES INC.**
 CHKD. BY _____ DATE _____ INSPECTION OF LAND
 SUBJECT Weymouth Pond, Drainage Area

SHEET NO. _____ OF _____
 PROJECT W-105

WEYMOUTH GREAT POND AREA ABOVE & BELOW ST.

READ #2	14.67	READ #3	31.80	54.94
" #1	<u>4.53</u>	" #2	<u>14.67</u>	<u>24.33</u>
	19.14		20.13	20.14

AREA = $20.14 (0.1435) = \underline{2.89 \text{ SQ MI.}}$

CLO SWAMP RIVER SWAMP AREA ABOVE TALBOT ST.

READ #2	116.09	READ #3	40.32	
" #1	<u>91.69</u>	" #2	<u>16.09</u>	
	24.40		24.43	

AREA = $24.42 (0.1435) = \underline{3.50 \text{ SQ MI.}}$

Copy available to DTIC does not
 permit fully legible reproduction

BY REP DATE 6-13-80 **LOUIS BERGER & ASSOCIATES INC.** SHEET NO. 1 OF 1
 CHKD. BY DATE PROJECT W-122
 SUBJECT WILTMAN FORD DALL, STORMING CAPACITY

COMPUTED SURCHARGE ELEV 68.00, AREA = 200 ACRES

$$VOL = 1/2 HA = 1/2 (68.0 - 55)(200) = 575 A-F$$

FROM OLD INVENTION SHEET VOL = 500 A-F

SAY VOLUME = 550 ACRES-FT


ELEV	AREA ACRES	AVE AREA	Δ VOL	TOTAL VOLUME	SURCHARGE VOLUME
68.0	200			550	
68	224	212	297	847	297
70	258	241	482	1329	779
72	299	278.5	557	1886	1336
74	340	319.5	634	2520	1975
76	381	360.5	721	3241	2696
78	422	401.5	803	4044	3499
80	463	442.5	885	4929	4384

Copy available to DTIC does not
 permit fully legible reproduction

5-3

ELEV IN FT.

STANDARD CROSS SECTION
10 X 10 TO THE HALF INCH



RESERVOIR AREA &
CAPACITY CURVES
WHITMANS POND DAM

SPILLWAY CREST ELEV 666

TOTAL STORAGE IN ACRES

AREA IN ACRES

SURFACE STORAGE


TOTAL STORAGE

TOP OF DAM ELEV 724

BY 234 DATE _____ LOUIS BERGER & ASSOCIATES INC. SHEET NO. 1 OF _____
 CHKD. BY _____ DATE _____ INSPECTION OF DAMS - MASS PROJECT _____
 SUBJECT WHITMAN POND RESERVOIR DAM - DISCHARGE CURVES

WHITMAN POND

PROFILE OF WATERWAY BELOW WHITMAN POND




IRON HILL DAM CONDUIT BELOW SIPHON


Assume conduit flows full above Sta 11+03 $L = 725'$

Conduit 9.5' wide x 10.5' high - $A = 99.75 \text{ sq. ft.}$ $r = 2.49 \text{ ft.}$ $r^3 = 1.85$ Average $n = 2.017$

Discharge Cfs	v	h_v	$S = \frac{1.49 v^{1.49}}{1.49 r^{4.49}}$	SL	$d + h_v + SL$	Elevation of gradient at Siphon outlet
2000	20.05	6.24	0.0155	11.25	11.25	45.15
2200	22.06	7.55	0.0188	13.62	31.67	48.83
2400	24.06	8.99	0.0224	16.20	35.69	52.85
2600	26.07	10.55	0.0263	19.02	40.07	57.23
2800	28.07	12.24	0.0305	22.05	44.79	61.75



D-6





Copy available to DTIC does not permit fully legible reproduction

SIPHON DISCHARGE - IRON HILL DAM
 $Q = CA \sqrt{2gH_T}$ $\frac{d}{D} = 1.0$ $\frac{R_c}{D} = \frac{3.07}{5} = 0.75 = C = 0.66$ (Fig. 297, Design of Small Dams)

Trial Disch. Q	Tailwater Elev.	Reservoir Elev.	Siphon #1 H_T	Siphon #1 ΔQ	Siphon #2 H_T	Siphon #2 ΔQ	Siphon #3 H_T	Siphon #3 ΔQ	Siphon #4 H_T	Siphon #4 ΔQ	$\sum Q$ Siphons	$Q_1 + Q_2$
-	-	59.88	12.88	521	0.4	4	0.3	3	0.2	2	530	530
-	-	59.98	12.98	524	12.88	521	0.4	4	0.3	3	1052	1077
-	-	60.08	13.08	526	12.98	524	12.88	521	0.4	4	1575	1605
-	47.0	60.18	13.18	528	13.08	526	12.98	524	12.88	521	2099	2135
2150	47.95	61.68	13.63	537.5	13.63	537.5	13.63	537.5	13.63	537.5	2150	2256
2200	48.90	63.17	14.27	550	14.27	550	14.27	550	14.27	550	2200	
2250	49.82	64.75	14.93	562.5	14.93	562.5	14.93	562.5	14.93	562.5	2250	2573
2300	50.80	66.40	15.60	575	15.60	575	15.60	575	15.60	575	2300	2769
2400	52.85	69.84	16.94	600	16.94	600	16.94	600	16.94	600	2400	3224
2500	55.04	73.48	18.40	625	18.40	625	18.40	625	18.40	625	2500	

Elev.	4	THRU OVER FLOW CREST $C = 3.1$ $L = 7.33$	Elev.	H	Flow over dam $C = 2.9$ $L = 200$ (Q_2)	Crest (Q_1)	$Q_1 + Q_2 + Q_3$ $\sum Q$
58.88	0	0	65.25	0	365	2265	2630
59.88	1.0	23	65.8	0.55	237	414	2933
60.18	1.3	34	66.40	1.15	715	430	3484
61.68	2.8	106	67.00	1.75	1343	526	4186
64.75	5.87	323	68.0	2.75	2645	626	5617
66.4	7.52	467	69.84	4.7	5732	524	8256
69.84	10.96	824			D-7		



$P = 6.5$ Seq $H_0 = 4$ $\text{Sec } C = 4$ $q = 5.4^2 \times 1.85 = 52$
 $d_2 = P + H_0 = 10.5$ $\text{Sec } C = 3.05$ $h_2 = 9.14$
 $\frac{h_2}{H_0} = \frac{9.14}{4.0} = 2.30$
 Small dams Fig 247 $k = 0.51 \times 1.85 = 1.85$
 For $x = 7.0$ $y = 5.73$
 $H_0 = \left[\frac{0.51(x)^{1.85}}{y} \right]^{1/1.85} = 4.0$

OVERFLOW OGG + FISH LADDER Q ₁							Over Dam Q ₂		
EL. 1.	H ₀	H ₀ /H _s	C ₀ *	C**	q ₁ /ft	L = 27'	EL. 72.4 L = 51'	H ₀ L	Q ₁ + Q ₂
66.6	0	-	-	-	0	0			0
67.6	1.0	0.25	0.86	3.27	3.27	98			98
68.6	2.0	0.50	0.92	3.50	9.90	268			268
69.6	3.0	0.75	0.96	3.65	18.77	512			512
70.6	4.0	1.00	1.00	3.80	30.46	821			821
71.6	5.0	1.25	1.03	3.90	43.60	1177			1177
72.4	5.8	1.45	1.05	4.00	55.87	1509	0	0	1509
73.0	6.4	1.60	1.07	4.07	65.90	1780	0.6	2.5	1839
74.0	7.4	1.85	1.08	4.10	82.53	2229	1.6	2.8	2518
76.0	9.4	2.35	1.09	4.14	119.31	3221	3.6	2.8	4196
77.5	10.9	2.73	1.09	4.15	149.34	4032	5.1	2.8	5677
78.5	11.6	2.9	1.09	4.15	163.90	4426	6.1	2.6	6424

* Fig 250 Small Dams
 ** $\frac{P}{H_0} = \frac{6.5}{4} = 1.625$ $C_0 = 0.97 \times 3.72 = 3.8$
 D-8

Copy available to DTIC does not permit fully legible reproduction

BY _____ DATE _____

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. 4 OF _____


CHKD. BY _____ DATE _____

INSPECTION OF DAMS - MASS.

PROJECT _____

SUBJECT WHITMAN POND RESERVOIR DAM - DISCHARGE CURVES

Siphon - Whitman Pond Dam



$$Q = CA \sqrt{2gH_T}$$

$$\frac{d}{D} = \frac{6}{5} = 1.20$$


$$\frac{R_c}{D} = \frac{35}{5} = 0.7$$

$$C = 0.68 \text{ (Fig 297 Small Dams)}$$

$$Q = 654.4 \sqrt{H_T}$$

RESERV. OVERFLOW ELEV. Q+Q2	Trial Throat Elev.	H _T (Average)	Siphon Disch. Q ₃	Q ₁ +Q ₂ +Q ₃	Actual T.W. Elev.	Remarks
65.6	0		0	0		
67.6	83	-	6.54	418	506	59.9 < Top of outlet OK
67.7	100	-	6.54	828	928	60.0 < " " " "
67.8	113	-	6.54	1265	1378	60.1 < " " " "
67.9	128	-	6.54	1693	1821	60.2 < " " " "
68.6	265	-	7.54	1797	2065	60.2 < " " " "
69.6	512	61.6	5.0	1851	2363	62.5 Too low
		62.0	7.12	1804	2316	62.1 OK
72.6	821	64.0	6.6	1681	2502	64.0 OK
71.6	1177	65.5	6.1	1616	2793	65.6 OK
72.4	1509	66.0	6.4	1656	3154	66.2 Too low
		66.1	6.3	1643	3152	66.1 OK (Top of dam)
73.0	1839	66.5	6.5	1668	3507	66.5 OK
74.0	2518	67.3	6.7	1694	4212	67.0 Too high
		67.1	6.9	1719	4237	67.1 OK
76.0	4196	68.3	7.7	1816	6011	68.3 OK
77.5	5677	69.0	8.5	1908	7535	69.1 OK

Copy available to DTIC does not permit fully legible reproduction



Copy available to DTIC does not
permit fully legible reproduction

BY REE DATE 4-1-80 LOUIS BERGER & ASSOCIATES INC.
CHKD. BY _____ DATE _____ INSPECTION OF DAMS
SUBJECT WHITMAN'S POND, HYDRO-PAY

SHEET NO. 1 OF _____
PROJECT W-192

DRAINAGE AREA (TOTAL) = 12.11 sq. mi
By INSPECTION RELEVANT = 25% = 3.0

LENGTH OF LONGEST WATER COURSE, $L = 3.63$ MI
 $L = 6.63$ MI

ELEV DIFFERENCE = $170 - 66 = 104$ FT

$$\% \text{ SLOPE} = \frac{104}{6.63} = 15.69 \text{ FT/MI} \quad \frac{1}{\sqrt{S}} = 3.46$$

$$\text{Now } \frac{LLC}{\sqrt{S}} = \frac{6.63 \times 6.63}{2 \times 3.46} = 5.55$$

$$\left(\frac{LLC}{\sqrt{S}} \right)^{.33} = (5.55)^{.33} = 1.76$$

$$LAG = K \left(\frac{LLC}{\sqrt{S}} \right)^{.33} = 1.76 K$$

ASSUME $K = 7.5$ HRS

REFER TO "CURVE 3" MOUNTAINOUS
REGION, WELL FORECASTED TOWARD
BON RES.

$$LAG = 7.5 (1.76) = 13.2 \text{ HRS}$$

$$T_p = 0.41 D + 0.82 LAG, \text{ WHERE } D = 1.0 \text{ HRS}$$

$$T_p = 0.41(1) + 0.82(13.2)$$

$$T_p = 0.41 + 10.82 = 11.23$$

Copy available to DTIC does not
permit fully legible reproduction

CHECK VELOCITY

$$T_c = \frac{T_p - .5 D}{0.6}$$

$$T_c = \frac{11.23 - .5}{0.6} = 17.55 \text{ HRS}$$

$$V = \frac{35,000}{19.5(2600)} = 0.5 \text{ FT/SEC}$$

O.K.

D-11

BY RFB DATE 4-1-80

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. 2 OF 2

CHKD. BY DATE

INSPECTION OF DRAIN

PROJECT W-103

SUBJECT WHITMAN'S POND DRAINAGE

$$T_r = 1.67 T_p = 1.67 (11.23) = 18.75 \text{ HRS}$$

$$T_b = T_p + T_r = 11.23 + 3.75 = 24.98 \text{ HRS}$$

q_p = PEAK RATE IN CFS

$$q_p = \frac{484 A Q}{T_p}$$

A = DRAINAGE AREA = 12.11 - 289

Q = RUNOFF IN INCHS

$$q_p = \frac{484 (9.22) (1)}{11.23} = 397 \text{ CFS}$$

FMP = PROBABLE MAXIMUM PRECIPITATION = 23.5 (1.3) = 18.8"

FOR WEYMOUTH, MAZ,

= 18.4 CONSIDERING INFILTRATION FOR


OVERLAND FLOW


FLOOD HYDROGRAPH FOR PMF

$q_p = 397 \text{ CFS}$

TIME (HOURS)	RAINFALL		Q CFS	TIME		
	%	INCHS		BEGIN	PEAK	END
0.0	-					
1.0	10	1.84	730	0	11.2	20
2.0	12	2.21	877	1.0	12.2	31
3.0	15	2.76	1096	2.0	13.2	32
4.0	33	6.79	2775	3.0	14.2	33
5.0	14	2.58	1024	4.0	15.2	34
6.0	11	2.02	802	5.0	16.2	35

Copy available to DTIC does not
permit fully legible reproduction





NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
WHITMANS POND DAM (MA..(U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV AUG 80

212

UNCLASSIFIED

F/G 13/13

NL

END


END
DATE


FILED

8-3

Fig. 3.

UNCLAS





SUBJECT ALBERTA, D.

INSPECTION OF DAMS

PROJECT W-53

STENO 200 ASSOCIATED PUBLIC RELATIONS ASSOCIATES, INC.

Water Surface @ Wagner Dam = 72.4, Q = 3.30
 " " " Iron Hill Dam = 66.1, Q = 3.30
 ΔH = 6.3 ft

$$Q = CAV = CAV\sqrt{2g\Delta h}$$

$$A = 5.3 \times 25 = 208 \text{ m}$$

$$Q = 0.7 (208) (2 \times 0.01 \times 0.01)^{1/2} = 5270 \text{ lb}$$

$$Q_{\text{TOTAL}} = 3150 + 3370 = 6520$$


Day $Q_{p, \text{TOTAL}} = 6500 \text{ LBS}$

Day Quantity = 3,200 lbs

SAY VALLEY STORIES BETWEEN DAM & N.Y. NIGHTS

$$\text{EQUALS } 1 \left(\frac{12+612}{2} \right) (2200) / 43560 + \frac{1000 \times 1000 \times 9}{43560} = 222 \text{ A.F.}$$

$$(\Delta V \text{ BETWEEN DAM \& BROAD ST}) + (\Delta V \text{ BROAD ST TO RR}) = \Sigma \Delta V$$




$$Q \text{ is } N \cdot 6560 \left(1 - \frac{222}{23000} \right) = 5790$$

Note 42 DIFFERENCE IN VOLUME BETWEEN
AFTER BAKING & BEFORE BAKING CONDITIONS

BY RFZ DATE 7-21-50 **LOUIS BERGER & ASSOCIATES INC.** SHEET NO. 2 OF 4
 CHKD. BY _____ DATE _____ INSPECTION OF _____ PROJECT W-193
 SUBJECT WHITMAN

Q @ N.Y.N.H. 5-22 = 5,780 cfs

ELEV. 42'



ELEV.	Box				PIPES			Q TOTAL
	HW	HW/D	Q/B	Q	HW	HW/D	Q	
26	19.3	1.75	175	1400	20	2.0	3200	4600
28	21.3	1.94	195	1560	22	2.20	3700	5060
30	23.3	2.12	210	1680	24	2.4	3800	5480
32	25.3	2.30	222	1776	26	2.6	4000	5776
34	27.3	2.48	233	1904	28	2.8	4200	6104
36	29.3	2.66	250	2000	30	3.0	4400	6400

FLOOD WATERS WILL POOL TO ELEVATION 32'
 BACKWATER TO APPROXIMATELY OLD NORTON MOTORS
 BUILDING

CHECK FLOODING, IF ANY FROM SIDEWAY Q
 WHAT IS Q CAPACITY @ TOP OF CHANNEL

17.5 15.8 1.16 115 920 14 1.4 3400 3320

WATER CONTAINED IN CHANNEL FOR 1/2 MILE/
 Q.

Copy available to DTIC does not
 permit fully legible reproduction

BY 352 DATE 7-2-80

CHKD. BY DATE

SUBJECT

LOUIS BERGER & ASSOCIATES INC.

INSPECTION OF DAM


SHEET NO. 3 OF 4

PROJECT W-105

FROM BOARD OF BANK ASSOCIATES PREPARED FOR
CAPITAL OF 1,000 CFS PER M&E REPORT

CAPACITY OF HERRING POND FROM PLEASANT
DAM TO BOARD ST. IS ABOUT 400 CFS PER
M&E REPORT.

FLOW DUE TO BREAK IN OLD HERRING POND
CHANNEL $6,500 - 2,500 = 4,000$ CFS



PLEASANT ST. CROSSING

ASSUME ΔH ACROSS S-CREST = 2 FT AND WEIR
FLOW OVER ROAD

STAGE	Q BOX	A, C=2.3	B, C=2.3
		ΔH L Q	ΔH L Q
8	350	0	0
10		1 80 184	2 60
12		2 160 1040	4 166
14	7	3 240 2870	6 304
11	350	1.5 120 510	3 107
	C, C=2.0		
	ΔH L Q		
8	0	0	
10	1	400 800	
12	2	800 4325	
14	3	1200 12870	
11	1.5	600 2200	
		Total	
		350	
		1050	
		5731	
		2800	

Copy available to DTIC does not
permit fully legible reproduction

D-18

BY REF DATE 7-21-80 LOUIS BERGER & ASSOCIATES INC. SHEET NO. 4 OF 4
 CHKD. BY DATE INSPECTION ST. DATE PROJECT W-38
 SUBJECT WATER MAINS & SEWER ANALYSIS

DEPTH OF FLOODING @ Pleasant St.
 ESTIMATED TO BE BETWEEN 3 1/4 FT

ESTIMATE OF FLOODING

Below Broad St.

PINGREE SCHOOL	±	7 FT
4 INDUSTRIAL BLDG	±	3 TO 4 FT
7 COMMERCIAL	±	3 TO 4 FT
1 HOUSE	±	3 TO 4 FT


COMMERCIAL ST. AREA


8 COMMERCIAL BLDG	1	TO 5 FT
3 HOUSES	1	TO 5 FT


PLEASANT ST. AREA

8 COMMERCIAL	1	TO 4 FT
3 HOUSES	1	TO 4 FT

Copy available to DTIC does not
 permit fully legible reproduction







APPENDIX E

INFORMATION AS CONTAINED
IN THE
NATIONAL INVENTORY OF DAMS

DATE
FILMED
-8